Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-025-10553	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name LANGLIE-MATTIX PENROSE SAND UNIT 33	
	OTHER			
2 Name of Operator ANADARKO PETROLEUM CORP.			8. Well No. 33-2	
3. Address of Operator		9. Pool name or Wildcat		
P.O. BOX 2497; MIDLAND, TX 79702			LANGLIE-MATTIX SR QN GRBG	
4. Well Location Unit Letter <u>C</u> : <u>33</u>	0 Feet From The NORTH	Line and231	.0 Feet From The WEST Line	
Section 33			NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)				
II. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
		REMEDIAL WORK		
	CHANGE PLANS			
PULL OR ALTER CASING CASING TEST AND CEMENT JOB				
OTHER:		OTHER:		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 8-14-97 Notified Gary Wink w/ OCD. Tagged up @ 3276'. Loaded hole and pumped 25 sx C cmt 3276-3113'. Loaded hole and pumped 25 sx C cmt 2457-2295'. Perforated @ 1250'. RIH w/ packer but unable to establish rate due to bad csg. POOH w/ packer and pumped 25 sx C cmt open-ended @ 1300'. Tagged plug @ 1203'. Perforated @ 185'. Pumped 40 sx C cmt @ 787' across bad csg w/ holes; no tag.
- 8-15-97 No tag on plug pumped @ 787'. Attempted to load hole w/ brine and pumped 30 sx C cmt w/ 3% CaCl₂@ 787'. WOC, and pressure-tested csg to 400 psi. Established circulation to surface and pumped 215 sx C cmt 185'-surface. RDMO
- 8-19-97 Cut off wellhead & capped well. Covered pit and dug up dead men. Installed dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowled, SIGNATURE	ge md belief. Engineer	
	DIL & GAS LEPECTOR	
CONDITIONS OF AFTROVAL, IF ANY:	ـــــــــــــــــــــــــــــــــــــ	× •

Anadarko Petroleum Corp. Langlie-Mattix Penrose Sand Unit #33-2 Lea County, New Mexico

08-14-97 Thursday

Notified Gary Wink w/ OCD of MI. MIRU Key rig. ND wellhead and NU BOP. RIH w/ 104 jts 2-3/8" workstring to 3276', tagged [reports indicate 25 sx plug at bottom, no CIBP's]. RU cementer and circulated hole w/ mud, pumped 25 sx C cmt 3276-3113'. POOH w/ tbg to 2457', loaded hole w/ mud and pumped 25 sx C cmt 2457-2295'. POOH w/ tbg. RIH w/ wireline and perforated @ 1250'. POOH w/ wireline. RIH w/ packer to 1197', had communication above packer. POOH w/ packer, bad casing 744-682'. SI 7" annulus, unable to establish rate. Released packer and POOH, RIH open-ended to 1300', pumped 25 sx C cmt @ 1300'. POOH w/ tbg and WOC. RIH w/ wireline and tagged cmt @ 1203'. POOH to 185' and perforated @ 185". POOH w/ wireline. Set packer, checked rate - 3 BPM on vacuum. POOH w/ packer, RIH w/ tbg to 787' and pumped 40 sx C cmt @ 787' across bad casing (holes in casing 744-682' taking fluid). POOH and SDFN.

RT: 7:30-6:30 11.0 hrs CRT: 11.0 hrs

08-15-97 Friday

RIH w/ tbg, no tag on plug pumped @ 787'. Attempted to load hole w/ brine, on vacuum. Pumped 30 sx C cmt w/ 3% CaCl₂ @ 787'. WOC 2 hrs. Pressure tested casing to 400 psi, okay. Opened surface casing, established circulation to surface. ND BOP and NU wellhead. Pumped 215 sx C cmt from 185' to surface, circulated cmt on annulus. RDMO to LMPSU #35-2. RT: 7:30-1:00 5.5 hrs CRT: 16.5 hrs

08-19-97 Tuesday

Cut off wellhead and capped well. Covered pit and dug up dead men. Installed dry hole marker.

Job #2202