Office Energy Minerals and Natural Resources	Form C-10 Revised March 25, 199
District I	WELL API NO.
1625 N. French Dr., Hobbs, NM 87240 District II OIL CONSERVATION DIVISION	30-025- <b>105</b> 73
811 South First, Artesia, NM 87210 District III  2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE X
District IV 2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No. LC-058626-A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:	7. Lease Name or Unit Agreement Name:
Oil Well X Gas Well Other	8. Well No.
2. Name of Operator	i
Anadarko Petroleum Corp.  3. Address of Operator	9. Pool name or Wildcat
P.O. Box 2497 Midland, TX 79702  4. Well Location	LANGLIE-MATTIX SR QN GRBG
Unit Letter I : 2310 feet from the SOUTH line and	990 feet from the EAST line
Section 34 Township 22S Range 37E	NMPM County LEA
10. Elevation (Show whether DR, RKB, RT, GR,	
20. 21	· Committee of the comm
11. Check Appropriate Box to Indicate, Nature of Notice	e, Report, or Other Data
11 1	IBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	<del></del>
	<u> </u>
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRIL	LLING OPNS.
THE CACING TEST AND	
PULL OR ALTER CASING	ID L_I
COMPLETION CEMENT JOB	
COMPLETION CEMENT JOB	give pertinent dates, including estimated date
COMPLETION CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER:  OTHER:	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
COMPLETION  CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
COMPLETION  CEMENT JOB  OTHER:  I. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attaon recompilation.  I. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  CIRC W/9.5# SALT GEL MUD.  SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
COMPLETION  CEMENT JOB  OTHER:  I. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  I. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  CIRC W/9.5# SALT GEL MUD.  SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.  PERF & SQZ 35 SX FROM 150' - SURFACE.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
COMPLETION  CEMENT JOB  OTHER:  I. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attaon recompilation.  I. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  CIRC W/9.5# SALT GEL MUD.  SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
COMPLETION  CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attaon recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion  "C" CMT ON CIBP @ 3230'. (CURRENTLY
COMPLETION  CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.  THE COMMISSION MUST BE NOT HE BEGIN	give pertinent dates, including estimated date ch wellbore diagram of proposed completion  "C" CMT ON CIBP @ 3230'. (CURRENTLY  OTIFIED 24 NNING OF
COMPLETION  CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.  THE COMMISSION MUST BE NOT HE BEGIN	give pertinent dates, including estimated date ch wellbore diagram of proposed completion  "C" CMT ON CIBP @ 3230'. (CURRENTLY  OTIFIED 24 NNING OF
COMPLETION  CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion  "C" CMT ON CIBP @ 3230'. (CURRENTLY  OTIFIED 24 NNING OF
COMPLETION  CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attaror recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.  THE COMMISSION MUST BE NOT HE BEGIN PLUGGING OPERATIONS FOR TO BE APPROVED.	OTIFIED 24 NNING OF THE C-103
OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attaror recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.  THE COMMISSION MUST BE NOT BE APPROVED.	OTIFIED 24 NNING OF THE C-103
OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attaon recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.  THE COMMISSION MUST BE NOT HEAD AND STALL P&A MARKER.  THE COMMISSION MUST BE NOT HEAD AND STALL P&A MARKER.	OTIFIED 24 NNING OF THE C-103
OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attaion recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.  THE COMMISSION MUST BE NOT HE BEGIN PLUGGING OPERATIONS FOR TO BE APPROVED.  hereby certify that the information above is true and complete to the best of my knowledge and be SIGNATURE.  TITLE_SR STAFF PRODUCTIONS TO THE BEGIN TO BE APPROVED.	OTIFIED 24 NNING OF THE C-103  CTION ENGINEER DATE 11/07/01  Telephone No. 915/683-0555
OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attaon recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAG.  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.  THE COMMISSION MUST BE NOT HE BEGIN PLUGGING OPERATIONS FOR TO BE APPROVED.  hereby certify that the information above is true and complete to the best of my knowledge and be	OTIFIED 24 NNING OF THE C-103  CUCTION ENGINEER DATE 11/07/01
OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attain or recompilation.  1. MIRU. TOH W/RODS & TBG. TAG CIBP. DUMP BAIL ADDITIONAL 6 SX CL HAS 3 SX.)  2. CIRC W/9.5# SALT GEL MUD.  3. SPOT 30 SX CL "C" CMT FROM 3120 - 2940'. WOC. TAG.  4. SPOT 25 SX CL "C" CMT FROM 2470 - 2323'.  5. PERF & SQZ 80 SX CL "C" FROM 1300 - 1100'. — TAGE  6. PERF & SQZ 35 SX FROM 150' - SURFACE.  7. CUT OFF CSG HEAD AND INSTALL P&A MARKER.  THE COMMISSION MUST BE NOT HE BEGIN PLUGGING OPERATIONS FOR TO BE APPROVED.  Thereby certify that the information above is true and complete to the best of my knowledge and be SIGNATURE  TITLE SR STAFF PRODUCTION.	OTIFIED 24 NNING OF THE C-103  CTION ENGINEER DATE 11/07/01  Telephone No. 915/683-0555

PLUGGING & ABANDONMENT WORKSHEET (3 STRING CSNG)

**OPERATOR** MALAREO LEASENAME LMPSU 37-04 WELL # 37 E TWN 225 SECT **FROM** N/S L FORMATION @ TD PENELSE TD: *₹6 &0* FORMATION @ PBTD7-RIVERA OPEN PBTD: SIZE SET @ TOC TOC DETERMINED BY 12:1/2 SURFACE 46 Cele @ 75% 100 INTMED 1 8 5/4 1175 466 Cele 1 753 TOC INTMED 2 Cele C 50% PROD 335 Y 2144 SIZE TOP BOT TOC DETERMINED B LINER 1 LINER 2 CUT & PULL @ TOP - BOTTOM INTMED 1 PERFS INTMED 2 OPERCHOLE PROD • REQUIRED PLUGS DISTRICT I PLUG TYPE SACKS RUSTLES (ANHYO) DEPTH PLUG CLOT YATE QUEEN EXAMPLES 7- FIVELS PLUGET OH 25 5765 9850 CHAYBURO SHOE 50 SXS 8700'-8800' 3052-56 SAN ANDRES PLU0#2 3116-20 PLUGES CIRP/35' 5300 CEP 25 535 5300 PLU041 CAPITAN REEP PLD044 STUB 50 SXS 4600'-4700' RETNR SOZ 200 575 400 DELAWARE PLUDES CIBP = 3230, 3s, SURF 711017 10.505 0-10 BELL CANYON CREEKLY CANYON PLUG AL 3230 6 5x 3120-2940 20012 BRUKEY CANYON 305 % CIBP @ 3300' 25 5x 2470 -2323 DOLLIFE SONOE PLUG # 3 805x 1300-1100 PLUGIE PLUGES 150 - 0 GLORIETA BLINEBRY PLUDE PLUD 6 7 tues DEDECARD PLUDIE PLUG#1 ABO PLUG 6 10 WC PLUGS PEDAY PLUGE STEASH ATOKA WORROW TD 3680 DEVOKAN

. 644 (.6576) 366-334