

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<input checked="" type="checkbox"/>		

March 26, 1949

Hobbs, New Mex.

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____
Skelly Oil Company H. O. Sims Well No. 16 in the _____

SW/4 SW/4 Company or Operator 34 223 Case 37E
Drinkard of Sec. _____, T. _____, R. _____, N. M. P. M.,
 _____ Field, _____ County.

The dates of this work were as follows: P.B. 6650 to 3670, 2/16/49; 3670 to surface, 3/25/49.

Notice of intention to do the work was (initials) submitted on Form C-102 on March 25, 1949
 and approval of the proposed plan was (initials) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED
 Drilled to total depth of 6650', no oil, gas or water encountered in Drinkard or Queens
 Sand sections. Was plugged and abandoned in the following manner:
 Spotted 50 sacks cement at 6650 then filled hole w/ heavy mud laden fluid to 5140'. Spotted
 50 sacks cement at 5140 and filled hole w/ heavy mud laden fluid to 3850'. Spotted 120 sacks
 cement at 3850 and filled hole w/ heavy mud laden fluid to 3525'. Spotted 20 sacks cement
 at 3525 then filled hole to 2700' w/ heavy mud laden fluid. (8-5/8" casing set at 2800' &
 cemented to surface) Spotted 20 sacks cement at 2700' then filled hole to 50' w/ heavy mud
 laden fluid. Filled hole from 50' to surface w/ 15 sacks cement, installed cement cap and
 4" pipe marker.

Witnessed by	<u>Mr. Bruce Connally</u>	<u>Hondo Drilling Company</u>	<u>Tool Pusher</u>
	<u>Mr. Geo. Baker</u>	<u>Cactus Drilling Company</u>	<u>Tool Pusher</u>
	Name	Company	Title

Subscribed and sworn before me this _____

26 th day of March 1949

Notary Public

I hereby swear or affirm that the information given above is true and correct.

Name R. J. DwyerPosition District SuperintendentRepresenting Skelly Oil Co.

Company or Operator

MY COMMISSION EXPIRES AUG. 19, 1952
 My commission expires _____

Address Drawer "D", Hobbs, New Mexico

Remarks:

APPROVED

MAR 2 1949

Roy Yankough
 Name

Oil & Gas Inspector

