

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-01167
7. Lease Name or Unit Agreement Name Shell "B" State
8. Well No. 1
9. Pool name or Wildcat Jalmat (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Maralo, Inc.	
3. Address of Operator P. O. Box 832, Midland, Texas 79702 0832	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>23-S</u> Range <u>36-E</u> NMPM <u>Lea</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3448	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10-1-91 Notified NMOCC of plugging operations. MI & RU pulling unit. Released pkr. POOH w/93 jts 2 3/8" tbg + pkr + 8 jts 2 3/8" tail pipe + SN + perf sub + mud anchor. LD 41 jts tbg.
- 10-2-91 RU Apollo WL. RIH w/gauge ring & junk basket. Could not bet below 3250'. Notified NMOCC & received approval from R. A. Saddler to set CIBP. RIH & set 5 1/2" CIBP @ 3220'. Mr. Saddler witnessed. Capped w/35' cement. Displaced hole w/10#/gal mud. Perf 4 squeeze holes @ 1650'. TIH w/tbg to 1650'. Spotted 40 sx cmt. plug. Pull above cement. Tag cmt at 1530'.
- 10-3-91 Perf 4 squeeze holes at 350'. Spotted 40 sx cmt plug @ 350'. Pull up above cmt & displace 25 sx outside perfs, left 15 sx inside csg. Spot 10 sx cmt plug @ surface. Removed wellhead. Weld on plate & dry hole marker. Cleaned up and leveled location. Well P&A'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Brenda Coffman TITLE Agent DATE 10-9-91

TYPE OR PRINT NAME Brenda Coffman TELEPHONE NO. 915 684-7441

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: