

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 030557a

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back on a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME NMPU
2. NAME OF OPERATOR Continental Oil Company	8. FARM OR LEASE NAME Farney A-17
3. ADDRESS OF OPERATOR Box 460 Hobbs, New Mexico	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1650' FWL of Sec. 17-23-36 Lea County, N. Mex. NMPM	10. FIELD AND POOL, OR WILDCAT Jalmat
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 17-23-36
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3475'	12. COUNTY OR PARISH Lea
	13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

PB & Recomplete

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The subject well was plugged back & recompleted using the following procedures:

Before: TD 3749'

Pay: Yates (3660'-98')

Perfs: 3660'-68', 3684'-98' W/4 Shots/foot

Well Shut In on 8-12-63

Work Done: Ran cmt retainer to 3650'. So perfs 3660'-3698' W/100 sx class "c" cmt. Perf @ 3619', 3622', 3625', 3627', 3632', 3634', 3636', & 3640' W/1 JSPP. Acidized perfs 3619'-3640' W/1000 gals acid. Fraced interval 3619'-3640' W/20,000 gal crude, 30,000# sd, 1,000# "ADOMITE" additives. Ran 115 lbs 2 3/8" tbg W/mud anchor & perf. nipple. Set @ 3600', Sn @ 3565'.

After: TD 3749' PB 3650'

Pay: Yates (3619'-40')

Well SI 8-1-66 Workover unsuccessful

Workover started: 6-6-65 Completed: 6-11-66

ILLEGIBLE

18. I hereby certify that the foregoing is true and correct

SIGNED

Hal R. Stephens

TITLE

Staff Supervisor

DATE 9-29-66

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

SEP 1 1966

*See Instructions on Reverse Side

J. L. GORDON

ACTING DISTRICT ENGINEER

USGS-5 FAN AM HOBBS-3 ATL ROS-2 CALIF MID-2 IPT

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner, or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well safe conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

887-851