NO. OF COPIES RECEIVE		
		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
h		5a. Indicate Type of Lease
U.S.G.S.		
LAND OFFICE		State Fee X
OPERATOR		5, State Oil & Gas Lense No.
	· ·	
	SUNDRY NOTICES AND REPORTS ON WELLS B FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. 014 WELL	NELL OTHER.	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Marathon	Dil Company	Edith Butler "A"
3. Address of Operator		9. Well No.
P.O. Box	2409 Hobbs, New Mexico 88240	7
4. Location of Well		10, Field and Pool, or Wildcat
т	1080 South ((0	
UNIT LETTER	1980 FEET FROM THE South 660 FEET FROM	Drinkard/Drinkard
THE West	LINE, SECTION 18 TOWNSHIP 22S RANGE 38E NMPM.	
mmmm	15. Elevation (Show whether DF, RT, CR, etc.)	
		12. County
İmmunu.	GL 3336'; KDB 3348'	Lea Alllllll
10.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
NC	TICE OF INTENTION TO: SUBSEQUENT	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ASANDON		ALTERING CASING
	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER Abandon Blinebry	/Recomplete as
OTHER	Drinkard	
17 Deveriby Developed a	Completed Operations (Clearly state all pertinent details, and give pertinent dates, including of	
work) SEE RULE 11	is.	estimated date of starting any proposed
1	Killed well Tratelled POP	
1.	Killed well. Installed BOP.	
2.	Pulled downhole equipment.	
2. 3.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522	
2.	Pulled downhole equipment.	
2. 3.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522	
2. 3.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours.	to
2. 3. 4.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570'	
2. 3. 4. 5. 6.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O	
2. 3. 4. 5. 6. 7.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log.	to K.
2. 3. 4. 5. 6.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68,	to K. 70,
2. 3. 4. 5. 6. 7. 8.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 Ja	to K. 70,
2. 3. 4. 5. 6. 7. 8. 9.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/l J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid.	to K. 70, SPF.
2. 3. 4. 5. 6. 7. 8.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a	to K. 70, SPF.
2. 3. 4. 5. 6. 7. 8. 9.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand.	to K. 70, SPF.
2. 3. 4. 5. 6. 7. 8. 9.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (to K. 70, SPF.
2. 3. 4. 5. 6. 7. 8. 9. 10.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested OF Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'.	to K. 70, SPF. and
2. 3. 4. 5. 6. 7. 8. 9. 10.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (to K. 70, SPF. and
2. 3. 4. 5. 6. 7. 8. 9. 10.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested OF Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'.	to K. 70, SPF.
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production.	to K. 70, SPF.
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested OF Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'.	to K. 70, SPF.
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production.	to K. 70, SPF.
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production.	to K. 70, SPF. and <u>a</u>
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production.	to K. 70, SPF. and <u>a</u>
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production.	to K. 70, SPF. and <u>a</u>
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production. Me information above is true and complete to the best of my knowledge and belief. Mathematical complete to the best of my knowledge and belief.	to K. 70, SPF. and 2
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production.	to K. 70, SPF. and <u>a</u>
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 18. I hereby certify that for the second secon	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production. TITLEPetroleum Engineer	to K. 70, SPF. and <u>a</u> bare <u>November 11, 197</u>
2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 18. I hereby certify that for the state of the st	Pulled downhole equipment. Ran RTTS packer on 2-3/8" tubing. Set RTTS packer @ 522 Squeezed Blinebry 5483'-5544' w/150 sx Class "C" cement 3000 psig. WOC 24 hours. Drilled out cement 5228' to 5544'. Cleaned out to 6570' Tested casing and cement squeeze to 1800 psig. Tested O Ran Gamma Ray/CNL/collar log. Perforated Drinkard zone 6438', 40, 48, 50, 57, 59, 68, 78, 92, 6504', 06, 10, 19, 21, 32, 36, 38, 50, 60. w/1 J Treated perfs 6438'-6560' w/4000 gallons 15% NE acid. Frac treated perfs w/20,000 gallons gelled 2% KCL water a 30,000# sand. Ran 2-3/8" tubing and Guiberson KVL packer. Set packer (6417'. Tested well. Placed well on production. TITLEPetroleum Engineer	to K. 70, SPF. and <u>a</u> bare <u>November 11, 197</u>

r.