

		RMATION ORLY PROVED Budger Burgau No. 1004-0135		
[]] [7] (A	RTMENT OF THE INTERIOR FOR INFO			
BUREA	U OF LAND MANAGEMENT	Expires: March 31, 1993		
	TICES AND REPORTS ON WELLS sals to drill or to deepen or reentry to a different reservoir.	5. Lease Designation and Serial No. LC032104		
	6. If Indian, Alottee or Tribe Name			
	TION FOR PERMIT " for such proposals			
	7. If Unit or CA, Agreement Designation			
1. Type of Well: OIL GAS WELL WELL	8. Well Name and Number BLINEBRY, A. H. FEDERAL NCT-1 /			
2. Name of Operator TEXACO EXI	12			
3. Address and Telephone No. P.O. BOX 73	9. API Well No.			
4. Location of Well (Footage, Sec., T., R., M	30-025-12140			
Unit Letter H : 1980 / Feet Fi	rom The NORTH Line and 989 Feet From The	10. Field and Pool, Exploaratory Area TUBB OIL AND GAS		
EAST Line Section 19	Township _22S Range 38E	11. County or Parish, State		
		LEA , NEW MEXICO		
Check Approp	riate Box(s) To Indicate Nature of Notice, R	eport or Other Data		
TYPE OF SUBMISSION		TYPE OF ACTION		
	Abandonment	Change of Plans		
	Recompletion			
Notice of Intent	Plugging Back	Non-Routine Fracturing		
Subsequent Report	Casing Repair	Water Shut-Off		
Final Abandonment Notice	Atlering Casing	Conversion to Injection		
	OTHER:	Dispose Water		
		(Note: Report results of multiple completion on Wet Completion or Recompletion Report and Log Form.)		
 Describe Proposed or Completed Operation work. If well is directionally drilled, give s 	ns (Clearly state all pertinent details, and give pertinent dates, is ubsurface locations and measured and true vertical depths for a			
		in markers and zones pertinent to this work,)*.		
 MIRU pulling unit. TOH w/rods and pun TIH w/7" CIBP and 7" packer on tbg. Set Pull bottom of tbg up hole to 5691' (bottod TIH w/7" cmt retainer on tbg. Set retaine TIH w/6-1/4" bit, 6 3-1/2" DC's on tbg. R MIRU wireline w/packoff. TIH w/dump b TIH w/GR-CCL and log from 6500'-5500 TIH w/GR-CCL and log from 6500'-5500 TIH w/4" casing gun and perforate the T TIH w/6K treating packer and SN. Place RU DS. Acidize Tubb perfs 6130'-6258 w/max. press=4000#. RD DS. Releas TIH w/10k treating packer and SN. Set RU DS. RU pressure relief valve on ba Frac Tubb perfs 6130'-6258' w/47,500 resin coated sand at an average rate of Flow back well until dies. Release pkr, TIH w/production tbg, pump and rods. If 	np. NU 3000# manual double ram BOP. Release tbg anchor, At CIBP above openhole section $@+/-6835'$. Im Blinebry perf). Spot 300 gallons 15% NEFE across perform r @+/-5575' (top perf @ 5591'). Squeeze Blinebry perfs 556 U reverse unit w/power swivel. Drill out cement retainer and c ailer and dump 35' cement on top of CIBP @ 6835' for new P (or minimum charge, whichever is greater). TOH w/log. ubb Oil & Gas w/2 JSPF, 120 deg. spiral phasing from 6130' bottom of packer at 6258' (lower most perf). Spot 300 gallons W/4000 gallons 15% NEFE carrying 264 7/8" 1.3 s.g. baltses e packer, run packer through perforated interval to knock off a packer @ +/- 6000'. Load backside and test packer to 500#. ckside set at 2000#. Place 500# on backside and monitor thm gallons 35# borate XLG 2% KCL carrying 153,000# 20/40 Ott 35 BPM w/max pressure not to exceed 8000# TOH and lay down 3-1/2" tbg and packer	TOH w/2-3/8" tbg. ated interval. Pull uphole and set @ +/- 5500". h1'-5691'. TOH. WOC. ement through perforated interval. TOH BTD = 6800'. TOH w/bailer. • 6258' (176 Shots) RD wireline. • 15% NEFE across perforated interval. alers with an average rate of 4-5 BPM- my ball sealers. TOH w/2-3/8" tbg.		
 MIRU pulling unit. TOH w/rods and pun TIH w/7" CIBP and 7" packer on tbg. Set Pull bottom of tbg up hole to 5691' (bottod TIH w/7" cmt retainer on tbg. Set retaine TIH w/6-1/4" bit, 6 3-1/2" DC's on tbg. R MIRU wireline w/packoff. TIH w/dump b TIH w/GR-CCL and log from 6500'-5500 TIH w/4" casing gun and perforate the T TIH w/6K treating packer and SN. Place RU DS. Acidize Tubb perfs 6130'-6258' w/max. press=4000#. RD DS. Release TIH w/10k treating packer and SN. Set RU DS. RU pressure relief valve on ba Frac Tubb perfs 6130'-6258' w/47,500 resin coated sand at an average rate of Flow back well until dies. Release pkr, TIH w/production tbg, pump and rods. I 	np. NU 3000# manual double ram BOP. Release tbg anchor, A CIBP above openhole section @ +/- 6835'. Im Blinebry perf). Spot 300 gallons 15% NEFE across perfora r @ +/- 5575' (top perf @ 5591'). Squeeze Blinebry perfs 555 U reverse unit w/power swivel. Drill out cement retainer and c ailer and dump 35' cement on top of CIBP @ 6835' for new P ' (or minimum charge, whichever is greater). TOH w/log. ub Oil & Gas w/2 JSPF, 120 deg. spiral phasing from 6130' e bottom of packer at 6258' (lower most perf). Spot 300 gallons '' w/4000 gallons 15% NEFE carrying 264 7/8' 1.3 s.g. ballser e packer, run packer through perforated interval to knock off a packer @ +/- 6000'. Load backside and test packer to 500#. ckside set at 2000#. Place 500# on backside and monitor thro gallons 35# borate XLG 2% KCL carrying 153,000# 20/40 Ott 35 BPM w/max pressure not to exceed 8000# TOH and lay down 3-1/2" tbg and packer. Place on test. TITLE	TOH w/2-3/8" tbg. ated interval. Pull uphole and set @ +/- 5500". M1'-5691'. TOH. WOC. ement through perforated interval. TOH BTD = 6800'. TOH w/bailer. - 6258' (176 Shots) RD wireline. a 15% NEFE across perforated interval. alers with an average rate of 4-5 BPM my ball sealers. TOH w/2-3/8" tbg. oughout job. iowa sand and tail in w/40,000# curable		
 MIRU pulling unit. TOH w/rods and pun TIH w/7" CIBP and 7" packer on tbg. Set Pull bottom of tbg up hole to 5691' (bottod TIH w/7" cmt retainer on tbg. Set retaine TIH w/6-1/4" bit, 6 3-1/2" DC's on tbg. R MIRU wireline w/packoff. TIH w/dump b TIH w/GR-CCL and log from 6500'-5500 TIH w/4" casing gun and perforate the T TIH w/6K treating packer and SN. Place RU DS. Acidize Tubb perfs 6130'-6258' w/max. press=4000#. RD DS. Release TIH w/10k treating packer and SN. Set RU DS. RU pressure relief valve on ba Frac Tubb perfs 6130'-6258' w/47,500 resin coated sand at an average rate of Flow back well until dies. Release pkr, TIH w/production tbg, pump and rods. I 	np. NU 3000# manual double ram BOP. Release tbg anchor, et CIBP above openhole section $@+/-6835'$. m Blinebry perf). Spot 300 gallons 15% NEFE across perform r $@+/-5575'$ (top perf $@5591'$). Squeeze Blinebry perfs 556 U reverse unit w/power swivel. Drill out cement retainer and c ailer and dump 35' cement on top of CIBP $@6835'$ for new P ' (or minimum charge, whichever is greater). TOH w/log. ubb Oil & Gas w/2 JSPF, 120 deg. spiral phasing from 6130' bottom of packer at 6258' (lower most perf). Spot 300 gallons V w/4000 gallons 15% NEFE carrying 264 7/8" 1.3 s.g. baltset e packer, run packer through perforated interval to knock off a packer $@+/- 6000'$. Load backside and test packer to 500#. ckside set at 2000#. Place 500# on backside and monitor thr gallons 35# borate XLG 2% KCL carrying 153,000# 20/40 Ott 35 BPM w/max pressure not to exceed 8000# TOH and lay down 3-1/2" tbg and packer. Place on test.	TOH w/2-3/8" tbg. ated interval. Pull uphole and set @ +/- 5500". h1'-5691'. TOH. WOC. ement through perforated interval. TOH BTD = 6800'. TOH w/bailer. • 6258' (176 Shots) RD wireline. • 15% NEFE across perforated interval. alers with an average rate of 4-5 BPM- my ball sealers. TOH w/2-3/8" tbg. oughout job. how a sand and tail in w/40,000# curable APR 1.2 1996 APR 1.2 1996		

DISTRICT I P.Q. Box 1980, Hobbs, NM 88241-1980 DISTRICT II P.O. Box Drawer DD, Artesia, NM 88211-0719 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 DISTRICT IV		State of New Mexico Energy, Minerals and Natural Resources Depail ont OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088			SION	Form C-102 Revised February 10,1994 Instructions on back Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies		
P.O. Box 20	988, Santa Fe, NM 875						_	ED REPORT
	¹ API Number		² Pool Code	·	AGE DEDICATI			·
	30-025-12140						l Name L AND GAS	
4	Property Code			⁵ Property Name			⁶ Well No.	
7	010899 ⁷ OGRID Number 022351		BLINEBRY, A. H. FEDERAL NCT-1 ⁸ Operator Name TEXACO EXPLORATION & PRODUCTION INC.				12 ⁹ Elevation 3374' GL	
						1C.		
			1	^o Surface Lo	cation			<u> </u>
Ul or lot no.			Lot.ldn Feet From The North/Sout 1980 NORT		North/South Line	Feet From The	East/West Line	County
Н	19 22				NORTH 989		EAST	LEA
UI or lot no	. Section Towns		Lot.Idn	and the second se	ifferent From Su		· · · · · · · · · · · · · · · · · · ·	·····
		ship Range	Lotian	Feet From The	North/South Line	Feet From The	East/West Line	County
16					989' 989'	I hereby contained h best of my I Signature	Vilcox chnician	nation plete to the
						I hereby cert on this plat actual surve supervision,	Seal of Surveyor	ion shown notes of fer my true and ge and