

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instruction
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER SALT WATER DISPOSAL

2. NAME OF OPERATOR
TEXACO INC

3. ADDRESS OF OPERATOR
P.O. BOX 728, HOBBS NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
UNIT LETTER L, 1980' FSL & 330' FWL

14. PERMIT NO.
30-025-12144

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3386' (DF)

5. LEASE DESIGNATION AND SERIAL NO.
LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
A.H. BLINERY FED NCT-1

9. WELL NO.
11

10. FIELD AND POOL, OR WILDCAT
SAN ANDRES

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC 28, T22S, R38E

12. COUNTY OR PARISH
LEA

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) CONVERT TO SWD

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU ON APRIL 28, 1987. PULLED RODS & PUMP.
2. PICKED-UP AND RAN 6 1/8" BIT AND SCRAPER TO 6840' TOH.
3. SETUP AND RAN 7" CIBP. SET CIBP @ 6837'. DUMPED 35' CMT ON TOP NEW PBTD 6802'.
4. LOAD HOLE w/ 2% KCL WTR. RAN 7" CIBP. SET CIBP @ 6205'. DUMPED 35' CMT ON TOP NEW PBTD 6170'. TEST CSG TO 500' 4. OKAY.
5. G.I.H. AND SET 7" CIBP @ 5200'. DUMPED 35' CMT ON TOP NEW PBTD 5165'.
6. PERFORATE SAN ANDRES POOL @ 4952'-54', 82'-90', 5015'-24', 28'-30' w/ 2.5 PF, 50 SHOTS.
7. TIH w/ 7" PKR ON 2 7/8" WORKSTRING. SET PKR @ 4798'. ACIDIZE SAN ANDRES PERFS w/ 2500 GALLONS 15% HCL AND 75 BALL SEALERS.
8. SWAB LOAD BACK.
9. TOH AND CHANGE WELLHEAD.
10. TIH w/ 7" BAKER TSN PKR & MODEL BUAWE AND 2 7/8" PLASTIC COATED TBG.
11. CIRC PKR FLUID.
12. RAN STEP RATE TEST MAY 8, 1987.
13. 24 HR TEST, DISPOSAL PRESSURE INCREASED TO 1250 PSI (SURFACE) - MAY 21, 1987.
14. SHUT WELL IN. EVALUATING PERFORATING OTHER SAN ANDRES PAY.

18. I hereby certify that the foregoing is true and correct

SIGNED KE Johnson

TITLE AREA SUPERINTENDENT

DATE JUN 02 1987

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD
DATE _____

JUN 11 1987

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

POSTAL

RECEIVED
JUN 15 1987
OCD
HOBBS OFFICE