	- A	· 2	
NO, OF COPIES RECEIVED			Form C-103
DISTRIBUTION	-		Supersedes Old
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			
U.S.G.S.			Sa. Indicate Type of Leaso
LAND OFFICE			State Fee X
OPERATOR			5. State Oll & Gas Lesse No.
an managan na ang mananan na pananang pangkanang pang pang pang pang pang pang pang			
SUNDRY NO OO NOT USE THIS FORM FOR PROPOSAL USE "APPLICATION FO	OTICES AND REPORTS ON	WELLS MCK TO & DIFFERENT RESERVOIR.	
1.			7. Unit Agreement None
WELL X WELL O	DTHER-		
2. Name of Operator			8. Farm of Lease Name
Gulf 0il Corporation	. .		Higgins
3. Address of Operator			9. Well No.
Box 670, Hobbs, New Mexic	. 88240		1
4. Location of Well			10, Field and Pool, or Wildcat
UNIT LETTER J 1980	South	1980	
UNIT LETTER,,	FEET FROM THE	LINE AND 1900 FEET FRO	M DI IIIRAI U
THE East LINE, SECTION	20 22-5	38	
The LINE, SECTION	TOWNSHIP 22-5	RANGE JOHA NMPI	* 61111111111111116
11111111111111111111111111111111111111			12. County
		3384' DF	Lea
16. Charles ton			
		ature of Notice, Report or O	
NOTICE OF INTEN	211014-10:	SUBSEQUEN	T REPORT OF:
.	·	· · · · · · · · · · · · · · · · · · ·	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ADANDON	· · · · · · · · · · · · · · · · · · ·	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
01HER			· · · · · · · · · · · · · · · · · · ·
11 Decelle Decentration		<u>Completed in Drink</u>	ard.
17, Describe Proposed or Completed Operatio work) SEF RULE 1103.	ma (Clearly state all pertinent dete	uils, and give pertinent dates, includin	g estimated date of starting any proposed

6660' PB, 7003' TD

Pulled producing equipment. Squeezed Paddock perforations 5180' to 5196' with 150 sacks of Class C cement. WOC 24 hours. Cleaned out and tested squeezed perforations with 500#, 30 minutes, OK. Cleaned out to 6845'. Perforated Drinkard zone in 7" casing with 4, 1/2" JHPF at 6720=22', 6737-39', 6776-78' and 6807-09'. Ran treating equipment and treated new perforations with 5,000 gallons of 15% NE acid. Swabbed water only. Pulled treating equipment. Set CI BP at 6670' and capped with 2 sacks of cement to 6660', abandoning Drinkard perforations 6720' to 6809'. Perforated Drinkard zone in 7" casing with 4, 1/2" JHPF at 6385-87', 6413-15', 6444-46', 6465-67', 6495-97', 6528-30' and 6554-56'. Ran treating equipment and treated new perforations with 3500 gallons of 15% NE acid. Frac with 60,000 gallons of gel brine and 68,000# sand. Maximum pressure 4400#, minimum 2900#, ISIP 1900#, after 15 minutes 1700#. AIR 20 BPM. Pulled treating equipment. Ran packer and 2-3/8" tubing. Set packer at 6342' with 10,000# compression. Swabbed and cleaned up and returned well to production.

19. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ISHED_ C. R. Kongelswa	TITLE Project Petroleum Engineer	'DATE March 26, 1976
APROVED BY Derry Lexton	STREET I	
ONDITIONS OF APPROVAY. IF ANY:	TITLE	DATE