

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR APPLICATIONS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☐ Fee ☒ 5. State Oil & Gas Lease No.																				
1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER ☒ Gas - Gas Dual		7. Unit Agreement Name																				
2. Name of Operator Gulf Oil Corporation		8. Form or Lease Name T. R. Andrews																				
3. Address of Operator Box 670, Hobbs, N.M. 88240		9. Well No. 2																				
4. Location of Well UNIT LETTER G 1980 FEET FROM THE north LINE AND 1980 FEET FROM THE east LINE, SECTION 32 TOWNSHIP 22S RANGE 38E N.M.P.M.		10. Field and Pool, or Wildcat Blinebry Gas-Tubb Gas																				
11. Elevation (Show whether DF, RT, GR, etc.) 3401' GL		12. County Lea																				
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data <table border="0"> <tr> <td colspan="2">NOTICE OF INTENTION TO:</td> <td colspan="2">SUBSEQUENT REPORT OF:</td> </tr> <tr> <td>PERFORM REMEDIAL WORK ☐</td> <td>PLUG AND ABANDON ☐</td> <td>REMEDIAL WORK ☐</td> <td>ALTERING CASING ☐</td> </tr> <tr> <td>TEMPORARILY ABANDON ☐</td> <td>CHANGE PLANS ☐</td> <td>COMMENCE DRILLING OPER. ☐</td> <td>PLUG AND ABANDONMENT ☐</td> </tr> <tr> <td>PULL OR ALTER CASING ☐</td> <td>OTHER ☐</td> <td>CASING TEST AND CEMENT JOBS ☐</td> <td></td> </tr> <tr> <td></td> <td></td> <td>OTHER Acidized ☐</td> <td></td> </tr> </table>			NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐	TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐	PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐				OTHER Acidized ☐	
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:																				
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐																			
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐																			
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐																				
		OTHER Acidized ☐																				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6390' PB. Pumped 1500 gallons 15% NEFE acid down tubing over Tubb perforations 6070' to 6275'. Flushed with 35 barrels brine water. Swabbed and cleaned up.

Pumped 1000 gallons 15% NEFE acid down tubing-casing annulus over Blinebry perforations 5580' to 5630'. Flushed with 100 barrels water. Maximum pressure 800#. Average injection rate 2 bpm. Swabbed and cleaned up - Blinebry zone would not flow - closed in.

Returned Tubb gas zone to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *G. T. Berlin* TITLE Area Engineer DATE 2-15-77

Orig. Signed by
Jerry Sexton

APPROVED BY Dist. L. S. TITLE DATE 17 1977

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 1 1977

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C.