

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-12184

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

T.R. Andrews

8. Well No.

3

9. Pool name or Wildcat

Blinebry

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Chevron USA, Inc.

3. Address of Operator 15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter J : 1980 feet from the south line and 1980 feet from the east line

Section 32

Township 22-S

Range 38-E

NMPM

County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Notify OCD 24 hrs prior to MI & RU.

2. Set 5 1/2 CIBP @ 5600' spot 20sx plug 5600-5500(Blinebry) WOC Tag.

3. Spot 25sx plug 3600-3400(Queen)

4. Cut 5 1/2 csg @ 3100', L/D csg.

5. Spot 100sx plug 3150-2700 (8 5/8 shoe, B-salt, Stub) WOC Tag

6. Spot 40sx plug 1400-1200(T-salt)

7. Perf 4 holes @ 320', sqz 125sx plug 320'-150' (13 3/8 shoe) WOC Tag.

8. 10sx surf, Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G.R. Bledsoe

TITLE HES Specialist

DATE 10/7/2002

Type or print name G.R. Bledsoe

Telephone No. 915.687.7153

APPROVED BY

TITLE

ORIGINAL SIGNED BY

PAUL F. KAUTZ

DATE

OCT 08 2002

Conditions of approval, if any:

PETROLEUM ENGINEER