

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-4467-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dual	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name T. R. Andrews
3. Address of Operator Box 670, Hobbs, New Mexico	9. Well No. 5
4. Location of Well UNIT LETTER A , 560 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 22-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Blinebry & Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3374 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Abandoned Drinkard and installed PE in Blinebry

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled both strings of tubing. Ran Model "DR" locator plug on WL and latched into Model D packer at 5905'. Dumped 30 gallons of pea gravel on DR plug. Filled 21' to 5884'. Dumped 2 sacks of Incoor Sulphate resistant cement on pea gravel. Had 11' of fill to 5873' new PWD. Ran 2-3/8" tubing and set at 5758'. Ran rods and pump and returned Blinebry zone to production. Drinkard zone now abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY

SIGNED **C. E. BORLAND**

TITLE **Area Production Manager**

DATE **June 24, 1965**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: