

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATION	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-70

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-9612

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State T
3. Address of Operator P.O. Box 68, Hobbs NM 88240	9. Well No. 2
4. Location of Well UNIT LETTER N 2310 FEET FROM THE West LINE AND 990 FEET FROM THE South LINE, SECTION 32 TOWNSHIP 22-S RANGE 38-E N.M.P.M.	10. Field and Pool, or Wildcat Paddock, South
15. Elevation (Show whether DF, RT, GR, etc.) 3389' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☒ Open additional pay and acidize

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to open additional Paddock pay and acidize as follows:
POH with production equipment. Check PBD, if necessary clean out to $\pm 5225'$. Perf 5183-5203' w/4JSF using a 3 1/8" gun. RIH with PPI pkr, collar locator, retrievable fluid plug, and work string. Test pkr against blank pipe. Lower pkr to $\pm 5220'$ and pump 20 bbls filtered 2% HCl fresh to clean out the. RIH with RFC valve on sand line. Break down perfs 5219-5183' 1 ft at a time with 50 gals/ft 15% NEFE HCl with additives. Pull up to $\pm 5130'$ and pump 700 gals 15% NEFE HCl w/add. Flush with 30 bbls filtered 2% HCl fresh. Retrieve RFC valve and fluid plug.
0+5 NMCD, H 1-JRB 1-FJN 1-GOC

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mary C. Clark TITLE Asst. Admin. Analyst DATE 1-8-85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

JAN 10 1985

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Swab and evaluate production. Release ~~pk~~ and P.O.H. RTH with production equipment. Land tlg at $\pm 5186'$. Return well to production.

RECEIVED

JAN - 9 1985

COO
HOBBS OFFICE