

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
A. H. Blinebry NCT-1

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

Paddock, South

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 33, T-22-S, R-38-E

12. COUNTY OR PARISH 13. STATE

Lea New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR TEXACO Inc.
3. ADDRESS OF OPERATOR P.O. Box 728, Hobbs, New Mexico 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 1980' from the North Line and 330' from the West Line of Section 33, T-22-S, R-38-E, Unit Letter E
14. PERMIT NO. Regular	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3380' GR

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

TEXACO Inc. proposes to do the following work on subject well:

1. Pump 1000 gals homogenized acid and 1000 gals LSTNE acid via casing and tubing annulus as follows: Pump 200 gals homogenized acid. Wait 10 minutes. Pump remaining 800 gals in 100 gal. stages w/10 minutes between stages. Follow last stage of homogenized acid w/1000 gals LSTNE acid.
2. Flush with treated fresh water.
3. Return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Assistant District

TITLE Superintendent

DATE March 23, 1971

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

MAR 25 1971

ARTHUR R. BROWN  
DISTRICT ENGINEER

\*See Instructions on Reverse Side

RECEIVED

MAR 10 1970

OIL CONSERVATION ACT  
SECTION 101