Form C-102 NEW MEXICO OIL C	ONSERVATION COMMISSION 7 194	
	ONSERVATION COMMISSION 7 194 FE, NEW MEXICO	/
The second section will be second section of the section of the second section of the	FOUR NOTICES SULLIV	50
Sec. 1	THE STORY	
Submit this notice in triplicate to the Oil Conservation of begin. A copy will be returned to the sender on which advisable, or the rejection by the Commission or agent, ed, and work should not begin until approval is obtained the Commission.	h will be given the approval, with any modifications of the plan submitted. The plan as approved should ed See additional instructions in the Rules and Regu	onsidere he follow
Indicate nature of	notice by checking below:	
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL	x
NOTICE OF INTENTION TO DEEPEN WELL		
Hobbs, Naw Mea	June 10, 1947	
	Place Date	
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico.		
Gentlemen:		
Following is a notice of intention to do certain work as Oil Company Brunson "B2		O NE SI
Company or Operator Lease of Sec. 3, T. 22 S, R. 37 E		
Tan	, N. M. P. M., Drinkard	Field
ounty.	DODOGED DI AN OF WORK	
	ROPOSED PLAN OF WORK S AND REGULATIONS OF THE COMMISSION	•
	a TD of 3615'. Applece of	
8 5/8" csg came loose in the hole at 250		
2653'. Admill was run in the hole to the could not be fished out or drilled out.		
load the hole with 10# mid, spot 25 sach A stain will be taken on the 8 5/8" casi and a plug put in hole at this point wit plugged at surface with 25 sacks cement	It is proposed to run tubing to 2658 as of cement at this point and plug. Ing-casing shot off at freeze point, the 25 sacks cement. Hole will then be	' ,
A stain will be taken on the 8 5/8" casi and a plug put in hole at this point with	It is proposed to run tubing to 2658 as of cement at this point and plug. Ing-casing shot off at freeze point, the 25 sacks cement. Hole will then be and a 4" marker left 4' out of the greater and	' ,
load the hole with 10# mid, spot 25 sach A stain will be taken on the 8 5/8" cast and a plug put in hole at this point wit plugged at surface with 25 sacks cement Approved	It is proposed to run tubing to 2658 as of cement at this point and plug. Ing-casing shot off at freeze point, th 25 sacks cement. Hole will then be and a 4" marker left 4' out of the grand a 4" m	onnd

Drawer Hobbs, New Mexico