

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

Offset Oper. co- Cont. vntal Oil Co.

TPC&Co.

(Form C-102)
(Revised 7/1/52)

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	XX	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico
(Place)

February 5, 1962
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Sinclair Oil & Gas Company State **157 "F"** Well No. **2** in **"H"**
(Company or Operator) Lease (Unit)
SE 1/4 NE 1/4 of Sec. 17, T. 23S, R. 36E, NMPM, Jalnet Gas Pool Pool
(40-acre Subdivision)
Lee County.

TO 3652FB
Plugging

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Reason for plugging- Production from present producing zones has exhausted
Well Completed as: 318' of 13"OD Casing cemented w/ 200 Sks.- cement circulated
3665' of 7"OD Casing cemented w/ 200 Sks.-
Perforations f/ 3624 to 3640

Propose to plug in following manner:

Set 25 Sk. cement plug f/ 3652 to 3575 and fill hole w/ heavy mud
Shoot off 7"OD Casing @ Approx. 2000' and set a 25 Sk. cement plug in top of 7"OD stub,
Set a 25 Sk. cement plug @ 1600' (top of salt,
Set a 15 Sk. cement plug in bottom of 13"OD Casing
and set regulation "Marker" in top of 13"OD Casing & bottom of cellar in 10 sacks cement
Marker extending 4' above surface level. Fill cellar & level location

Pull all casing shot off.

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....
Title.....

Sinclair Oil & Gas Company
Company or Operator

By.....

Position..... **Dist. Supt.**
Send Communications regarding well to:

Name..... **W. F. Burns,**

Address..... **520 E. Broadway, Hobbs, N.M.,**