

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.

Copy to O. & C.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR TEXACO, Inc.		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR P.O. Box 728, Hobbs, New Mexico 88240		8. FARM OR LEASE NAME A. H. Blinebry Fed. NCT-3	
4. LOCATION OF WELL (Report location clearly and in accordance with any State Requirements. See also space 17 below.) At surface 2306' FNL, 660' FNL, Sec. 31, T-22-S, R-38-E, Unit Letter 'E', Lea County, New Mexico		9. WELL NO. 3	
14. PERMIT NO. Regular		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3317' (DF)	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		10. FIELD AND POOL, OR WILDCAT Blinebry, Drinkard, Brunson Ellenburger 50.	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 31, T-22-S, R-38-E	
18. I hereby certify that the foregoing is true and correct		12. COUNTY OR PARISH Lea	
SIGNED _____		13. STATE New Mexico	

NMOCC CASE NO. 5628, ORDER NO. R-5170

1. Rig up. Pull rods & pump from Drinkard string. Install BOP. Shut-in Blinebry.
2. Fish junk from Blinebry string (60' sand line, sinker bar, swab & swab cup).
3. If fishing job successful perforate 2 7/8" Blinebry string w/1-JSPF from 7616' - 7621' in Ellenburger Formation.
4. If fishing job unsuccessful pull RBP in Drinkard string @ 6600' & clean out to TD of 7641'. This will open Ellenburger perms. that were below plug. Perforate 2 7/8" Drinkard string w/1-JSPF from 5731' - 5734' in Blinebry formation.
5. Acidize perms w/500 gal. 15% NE Acid.
6. Install pumping equipment. Test & place on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE: Asst. Dist Supt.

DATE 6-3-76

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUN 8 1976

BERNARD MOROZ

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side