

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>3002520283</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>B-934</b>
7. Lease Name or Unit Agreement Name <b>NEW MEXICO S STATE</b>
8. Well No. <b>25</b>
9. Pool name or Wildcat <b>BLINEBRY OIL</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3357 GL</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORMC-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator <b>EXXON CORPORATION</b>
3. Address of Operator <b>ATTN: REGULATORY AFFAIRS P. O. BOX 1600 MIDLAND, TX 79702</b>	4. Well Location Unit Letter <b>N</b> : <b>810</b> Feet From The <b>SOUTH</b> Line and <b>2130</b> Feet From The <b>WEST</b> Line Section <b>2</b> Township <b>22S</b> Range <b>37E</b> NMPM <b>LEA</b> County

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **ADD ABO PERFS** *alt perfs* ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-19-91 SET CIBP @ 6200 FT DUMP BAIL 20' CMT ON TOP (STRING #1 )  
3-22-91 PERF BLINEBRY 5672 TO 5814 54 SHOTS (STRING #1)  
3-23-91 ACIDIZE PERFS W 2100 GALS 15% HCL (STRING #1)  
3-25-91 STARTED FRAC JOB, DISCOVERED COMMUNICATION BETWEEN STRING #1 & 2  
SHUT WELL IN  
5-15-91 PERF ABO 6520 TO 7155 41 SHOTS (STRING #2) NO PRODUCTION  
7-16-91 SET RBP @ 6000' (STRING #2)  
7-24-91 SWAB STRIN #2 BROKE WIRELINE LEFT FISH IN HOLE  
PRODUCTION TEST STRING #2 BLINEBRY NO PRODUCTION  
WELL SHUT IN

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Sharon B. Timlin* TITLE **Sr. staff office assistant** DATE **05/01/92**

TYPE OR PRINT NAME **Sharon B. Timlin** (915) 688-7509 TELEPHONE NO.

(This space for State Use)

Orig. Signed by  
**Paul Kautz**  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE **05/06/92**

CONDITIONS OF APPROVAL, IF ANY:

*34 A BRYAN*