

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-20342	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name SCARBOROUGH ESTATE	
8. Well No. 8	
9. Pool name or Wildcat TUBB OIL AND GAS	
4. Well Location Unit Letter <u>L</u> : <u>1830'</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>31</u> Township <u>22S</u> Range <u>38E</u> NMPM <u>LEA</u> County	10. Elevation(Show whether DF, RKB, RT, GR, etc.) <u>3579' GL</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location
Unit Letter L : 1830' Feet From The SOUTH Line and 660 Feet From The WEST Line
Section 31 Township 22S Range 38E NMPM LEA County

10. Elevation(Show whether DF, RKB, RT, GR, etc.)
3579' GL

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
CASING TEST AND CMT JOB ☐
OTHER: PLUG BACK TO TUBB. ☒

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 1-4 THRU 1-21-93
MIRU PU, POOH W/RODS & PMP. ND WH,NU BOP. POH W/PROD TBG. RIH &
SET CIBP @ 7795, DUMP 35' CMT ON TOP. TST CSG TO 500# F/5807-CIBP, OK.
SET CICR @ 5528, TST TBG TO 3500# & CSG TO 500#, OK. SQZ BLINEBRY PERFS
W/125 SX CMT. TAG TOC @ 5525, DRL OUT CICR & CMT TO 6258, CIRC. PERF
TUBB 6223-5916,2 JHPF, 42 HOLES. SPOT 250 GALS 15% ACID, ACDZ NEW TUBB PERFS
W/3000 GALS 15% NEFE HCL. SWAB. FRAC W/41,000 GAL MY-T-GEL & 100,000#
16/30 SAND. FLOW BACK. (ABANDONED BRUNSON ELLENBURGER, SOUTH & BLINEBRY)
TURN OVER TO PRODUCTION

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT

DATE: 4/28/93

TYPE OR PRINT NAME NITA RICE

TELEPHONE NO. (915)687-7436

ORIGINAL SIGNED BY JERRY DEXTON

APPROVED BY JERRY DEXTON TITLE DIRECTOR

CONDITIONS OF APPROVAL, IF ANY:

DATE APR 30 1993