

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E & P Inc.

3. Address and Telephone No.

P.O.Box 3109 Midland, Texas 79702 (915) 688-4492

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit M, 990 FSL, 990 FWL, Sec 31-22S-38E

5. Lease Designation and Serial No.
LC032104

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

A.H. Blinebry Fed NCT 4-4

9. API Well No.

30-025-20921

10. Field and Pool, or Exploratory Area

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

7-20-98--Inform BLM of intent to plug well, MIRU, lay down rods

7-21-98--POOH w/half of tubing, wireline not available

7-22-98--Set 2 7/8" CIBP @ 6530', Y string--Set 2 7/8" CIBP @ 5420', X string

7-23-98--RIH w/tbg, tag CIBP @ 5430, X string, would not circulate, pump 20 sx cement, WOC

7-24-98--RIH tag, no cement, BLM okayed to set 25 sx cement, WOC, no tag, BLM okayed to set CIBP @ 5200 in X string

7-27-98--RIH w/tbg, tag CIBP @ 6530, Y string, Spot 5 sx on top, mix salt gel and pump, Spot 15 sx cement @ 5630' Y string WOC 4 hrs

RIH tag cement @ 5600', spot 15 sx cement @ 5600', Y string

7-28-98--RIH, tag no cement, BLM okayed to set CIBP @ 5200', Y string, tag CIBP @ 5200' in Y string and spot 10 sx cement, POOH

and RIH of X string and tag CIBP @ 5200' and spot 10 sx cement, POOH

7-29-98--RIH X string, tag cement @ 5097' POOH, RIH Y string, set down @ 2730', POOH, R/U wireline and RIH set down @ 2600'

7-30-98--Casing not free, RIH w/tbg to 2650' Y string, spot 10 sx cement, WOC 4 hrs, RIH tagged no cement, spot 15 sx cement SION

7-31-98--RIH to tag cement, no tag, POOH, RIH w/packer, pressure test to 3000#, good, POOH, okayed by BLM to spot 20 sx cement

@ 2650'

8-03-98--RIH tag cement @ 880', RIH X string to 2650' spot 15 sx cement, cut X string @ 1289', casing not free, pump 50 sx cement into

cut @ 1289', displace to 1050', WOC

8-04-98--Pressure test cement plug in X string to 1000 PSI, good, tag cement @ 1040', cut X & Y strings @ 250'. Lay down 2 7/8", Mix

and pump 100 sx cement to surface in 8 5/8" casing

8-05-98--RDMO

14. I hereby certify that the foregoing is true and correct

Signed

Russ Light

Title Manager, P&A, Dawson Production Services

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

APPROVED
PETER W. CHESTER
SEP 2 1998
BUREAU OF LAND MANAGEMENT
ROSWELL, NM
SOURCES AREA