State of New Mexicorgy, Minerals and Natural Resources Departm.

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO. 30-025-21059

| DISTRICT II Santa Fe, New Mexico 87504-2088 | 30 023 21033 |
|--|---|
| DISTRICT II Santa Fe, New Mexico 8/304-2088 P.O. Drawer DD, Artesia, NM 88210 | 5. Indicate Type of Lease STATE X FEE |
| DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 | 6. State Oil & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | 7. Lease Name or Unit Agreement Name |
| 1. Type of Well: | Shaha A A/C 1 |
| WELL X WELL OTHER | State A A/C 1 |
| 2. Name of Operator Clayton W. Williams, Jr., Inc. | 110 |
| 3. Address of Operator | 9. Pool name or Wildcat |
| 6 Desta Drive, Suite 3000 Midland, Texas 79705 | Langlie-Mattix, SR-Qu-GB |
| 4. Well Location | 550 Feet From The East Line |
| Unit Letter H: 1980 Feet From The North Line and | 550 Feet From The Last Line |
| Section 13 Township 23S Range 36E | NMPM Lea County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | |
| 3377 GL | |
| 11. Check Appropriate Box to Indicate Nature of Notice, | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT | |
| PULL OR ALTER CASING CASING TEST AND | CEMENT JOB |
| POLE ON ALTEN GROWN | |
| OTHER: OTHER: | |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inwork) SEE RULE 1103. | cluding estimated date of starting any proposed |
| 12/16 to 12/28/92 | |
| 1) Set CIBP @ 3450'. Dump bail 42' of cement on CIBP. | |
| 2) Circulate hole w/10# gelled brine from CIBP to surface. | |
| Perforated 4-1/2" csg @ 350', 2 SPF. Pumped 75 sx Class "C" cement and up 4-1/2 7-5/8' annulus. Circulated 10 sx to surface. | t w/2% CaCl2 down 4-1/2" casing |
| 4) Cut 7-5/8" & 4-1/2" casing 3' felow GL and welded on PNA marker. (GL. Cleaned location. | Cut anchors 3' below |
| See Attached Wellbore Diagram | |
| ^ | |
| | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. | 04 (05 (02 |
| SIGNATURE Petroleum En | gineer DATE 01/06/93 |
| TYPE OR PRINT NAME David Grafe | ТЕЦЕРНОМЕ NO. 682-6324 |
| | |
| (This space for State Use) | Ale contacts these day 21 |

CONDITIONS OF APPROVAL, IF ANY: