

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-746
7. Lease Name or Unit Agreement Name Brinninstool
8. Well No. 1
9. Pool name or Wildcat Wildcat
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3662.5' GR, 3689' RKB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Bettis, Boyle and Stovall
3. Address of Operator P. O. Box 1240, Graham, Texas 76046
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 16 36 Township 23-S Range 32-E NMPM Lea County

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging operations began on May 24, 1989, and were completed on June 12, 1989.

Set 25 sack plug at 13,180', WOC, tagged plug at 13,074'. Circulated hole with 9.5#/gallon mud. Set 50 sack plug at 8850', tagged plug at 8754'. SI overnight. On May 31, 1989 bled off gas for 2 minutes, both plugs leaking. Drilled out both plugs to 13,010', circulated hole with 10#/gallon brine. Spotted 200 sack plug from 13,010' to 12,175'. Set CIBP at 8555' with 25 sacks cement on top.

Jet-cut 7-5/8" casing at 6025' and pulled 142 joints (5714') of casing.

On June 9, 1989 continued to set cement plugs: 25 sacks at 7440', 25 sacks at 7240', 25 sacks at 6490', and 35 sacks at 6070'. Shut down for weekend.

Continued on June 12, 1989 setting cement plugs: 50 sacks at 5022', 50 sacks at 4780', 75 sacks at 1210', and 10 sack plug at surface with dry hole marker.

The anchors were cut-off and location cleaned up on June 12, 1989.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim Sigon TITLE Production Asst. DATE 9/5/89

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

API 20-025-21081