

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

V-746

7. Lessee Name or Unit Agreement Name

Brinninstool

8. Well No.

1

9. Pool name or Wildcat

Wildcat-Atoka

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

OAS
WELL ☒

OTHER

2. Name of Operator

Bettis, Boyle & Stovall

3. Address of Operator

P. O. Box 1240, Graham, Texas 76046

4. Well Location

Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 36 Township 23-S Range 32-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in. Rig up. Round trip tubing to 13050' and spot 200 sks. of cement.
2. Rig up wireline and set CIBP @ 8055'. 7 5/8 w/ 25 sks. of cement on top.
3. Run tubing to 7440' and spot 25 sks. of cement.
4. Spot 25 sks. of cement @ 7240'.
5. Spot 25 sks. of cement @ 6490'.
6. Spot 35 sks. of cement @ 6070'. WOC & tag @ 5965'. Pulled ± 6025' of 7 5/8" casing.
7. Spot 50 sks. of cement @ 4780'.
8. Spot 75 sks. of cement @ 1210'.
9. Spot 10 sks. of cement @ surface.
10. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE P & A Supv., Baber Well Servicing DATE 7-10-89

TYPE OR PRINT NAME Raymond Maldonado TELEPHONE NO. 505-393-5516

(This space for State Use)

APPROVED BY R A Hulse TITLE OIL & GAS INSPECTOR DATE SEP 25 1989

CONDITIONS OF APPROVAL, IF ANY:

44-111-12

100-111-12

RECEIVED
JUL 11 1965
OCD
MOBRS OFFICE