P. O. Box 198 Hobbs, NM 8 District II - 6 811 S. First Artesia, NM District III - 1000 Rio Bra Aztec, NM 8	88241-1980 Energy Minerals and Natural Resources Partment Originated 11/1/95 (505) 748-1283 Oil Conservation Division Submit Original 88210 2040 South Pacheco Street Submit Original (505) 334-6178 Santa Fe, New Mexico 87505 Submit Original 7410 (505) 827-7131 H - D310 K
	APPLICATION FOR QUALIFICATION OF WELL WORKOVER PROJECT AND CERTIFICATION OF APPROVAL
	E COPIES OF THIS APPLICATION AND ALL ATTACHMENTS MUST BE FILED WITH THE APPROPRIATE DISTRICT E OF THE OIL CONSERVATION DIVISION.
1.	Operator: Citation Oil & Gas Corp OGRID #:004537
	Address:8223 Willow Place South, Suite 250, Houston, Texas 77070-5623
	Contact Party: Debra Harris Phone: (281) 469-9664
11.	Name of Well: Antelope Ridge #3 API #:30-025-21082 Location of Well: Unit Letter K,1980 Feet from the South line and1650 feet from the Section34, Township33, Range34E, NMPM, Lea County
111.	Date Workover Procedures Commenced: 4/15/97 Date Workover Procedures were Completed: 5/1/97
IV.	Attach a description of the Workover Procedures undertaken to increase the projection from the Well.
V.	(From C-103 Attached) Attach an estimate of the production rate of the Well (a production decline curve or other acceptable method, and table showing monthly oil and/or gas Project Production) based on at least twelve (12) months of established production which shows the future rate of production based on well performance prior to performing Workover.
VI.	Pool(s) on which Production Projection is based:
	Morrow - 12,838' - 12,959'
VII.	AFFIDAVIT:
	State ofTexas)
) ss. County of <u>Harris</u>)
	Debra Harris, being first duly sworn, upon oath states:
	 I am the Operator or authorized representative of the Operator of the above referenced Well.
	 I have made, or caused to be made, a diligent search of the production records which are reasonably
	available and contain information relevant to the production history of this Well.
.1992.43	3. To the best of my knowledge, the data used to prepare the Production Projection for this Well is complete and accurate and this projection was prepared using sound petroleum engineering productes. (Name) Debra Harris
	Regulatory Analyst

SUBSCRIBED AND SWORN TO before me this 2011 day	of Mary 19	17 12 Harrell
My Commission expires:	Notary Public	RENEE HARRELL Notary Public, Blade of Taxas Ny Commission Expires March 2, 1990

FOR OIL CONSERVATION DIVISION USE ONLY:

VIII. CERTIFICATION OF APPROVAL:

This Application for Qualification of Well Workover Project is hereby approved and the above referenced Well is designated as a Well Workover Project pursuant to the "Natural Gas and Crude Oil Production Incentive Act" (Laws 1995, Chapter 15, Sections 1 through 8). The Oil Conservation Division hereby verifies the Production Projection for the Well Workover Project attached to this application. By copy of this Application and Certification of Approval, the Division notifies the Secretary of the Taxation and Revenue Department of this Approval and certifies that this Well Workover Project has been completed as of 5 - 1 - 7 - 19.

District Supervisor, District **Oil Conservation Division**

Date: ____7 /

IX. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT.

DATE: _____

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department Form C-103 Revised 1/1/89

DISTRICT I 2040 Pa	WELL API NO.		
P.O. Box 1980, Hobbs, NM 88240 Santa Fe,	30-025-21082		
DISTRICT II		5. Indicate Type of Lease	
P.O. Drawer DD, Artesia, NM 88210		STATE FEE	
DISTRICT III		6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410		E-8078	
SUNDRY NOTICES AND REPORTS ON	WELLS		Ş
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE	7. Lease Name or Unit Agreement Name	day seve	
DIFFERENT RESERVOIR. USE "APPLICATION FO			
(FORM C-101) FOR SUCH PROPOSALS	.)	4	
1. Type of Well: OIL GAS Z			
WELL GAS WELL OTHER		Antelope Ridge Unit	
2. Name of Operator Citation Oil & Gas Corp.		8. Well No.	
3. Address of Operator		3	
8223 Willow Place South, Suite 250, Houston, Texas 77	070-5623	9. Pool name or Wildcat Antelope Ridge Devonian	
4. Well Location		Antelope Ruge Devolitan	
Unit Letter K : 1980' Feet From The Se	outh Line and 16	50' Feet From The West I.	ine
			inic
Section 34 Township 23S	Range 34E	NMPM Lea Coun	ntv
	whether DF, RKB, RT, GR, etc)	internet a design of the second of	S.
3490' DF			
11. Check Appropriate Box to Ind	icate Nature of Notice,	Report, or Other Data	
NOTICE OF INTENTION TO:		SEQUENT REPORT OF:	
TEMPORARILY ABANDON CHANGE PLANS		OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CASING TEST AND CEN		
			-
OTHER:			
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen			
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103.	DTHER:	including estimated date of starting any proposed	
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW	dn ann. ND 11"10M WH	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freent. RIH	
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30	dn ann. ND 11"10M WHJ 070'. Dmp'd 35' "H" cmt 1	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 4.230'-265' in 4-1/2" lnr. RIH w/6" hit &	6
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set	dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7"	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" Inr. RIH w/6" bit & pkr & SN on tbg: pkr @6009', tst'd 7" In	: 6 .r
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13	DTHER: t details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" Inr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" In ann, pkr @8211, PIR w/3 bpm @150# - s	: 6 r g:
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd	OTHER: t details, and give pertiment dates, dn ann. ND 11"10M WHI 70'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2'	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab. 10 gals	: 6 r g:
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH	OTHER: t details, and give pertiment dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2'	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals ' WL entry guide. "XN" nipple, tbg sub.	: 6 ir g;
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" hipple, 5-1/2" mill-out ext & 7" BWB pkr on WL;	OTHER: t details, and give pertinent dates, dn ann. ND 11"10M WHJ 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' d	: 6 ir g; &
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid	OTHER: <i>t details, and give pertinent dates,</i> <i>dn ann. ND 11"10M WHI</i> 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 its 2-7/8" tbg to 12.711': tst'c	: 6 ir g; &
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of	OTHER: <i>t details, and give pertinent dates,</i> dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo on tbg. Instl'd wrap-aroun	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 4,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c id in WH; latched into pkr @12,725'.	: 6 ir g; &
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FJ	OTHER: t details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Per	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH [4,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals ' WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c id in WH; latched into pkr @12,725'. Pd Morrow "A" & "B": 12,838'-846':	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd F1 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL	OTHER: <i>t details, and give pertinent dates,</i> dn ann. ND 11"10M WHI 70'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Pert 911,200'. Loaded tbg w/3"	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH [4,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; 6 KCl wtr; loaded ann & 13-3/8" csg (via	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" hipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FI 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490	DTHER: t details, and give pertinent dates, t details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Pert 11,200'. Loaded tbg w/3° 0# w/3% KCl wtr. ISITP 4	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c id in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; & KCl wtr; loaded ann & 13-3/8" csg (via 4900#; 5 min 4450#. Swab'd perfs: SFL-	: 6 ir g; & 1
 OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" hipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd Fl 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize 	OTHER: t details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Per 11,200'. Loaded tbg w/3? 0# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c tod in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; 6 KCl wtr; loaded ann & 13-3/8" csg (via 1900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT	: 6 ir g; & 1
 OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd F1 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top particular distance of the surf of the surf	DTHER: details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Per 11,200'. Loaded tbg w/3? 0# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/2 erf. 2nd stage - flush 2-7/8'	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals "WL entry guide, "XN" nipple, tbg sub, nipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; ' KCl wtr; loaded ann & 13-3/8" csg (via 4900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959':	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FJ 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top po Max P - 5600#; Min P - 5370#; AIR 2.3 bpm; ISIP 473	DTHER: details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Per 11,200'. Loaded tbg w/3? 0# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/2 erf. 2nd stage - flush 2-7/8'	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals "WL entry guide, "XN" nipple, tbg sub, nipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; ' KCl wtr; loaded ann & 13-3/8" csg (via 4900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959':	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FI 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top po Max P - 5600#; Min P - 5370#; AIR 2.3 bpm; ISIP 473 MCFPD; TP 70; 24/64" ck.	OTHER: <i>t details, and give pertinent dates,</i> <i>dn ann.</i> ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r <i>e, seal assy & 4" J-latch lo</i> on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Per 11,200'. Loaded tbg w/3' 0# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/- erf. 2nd stage - flush 2-7/8' 1#; 15 min SIP 4345#. Sell	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals "WL entry guide, "XN" nipple, tbg sub, nipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; ' KCl wtr; loaded ann & 13-3/8" csg (via 4900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959':	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FJ 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top po Max P - 5600#; Min P - 5370#; AIR 2.3 bpm; ISIP 473	OTHER: <i>t details, and give pertinent dates,</i> <i>dn ann.</i> ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r <i>e, seal assy & 4" J-latch lo</i> on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Per 11,200'. Loaded tbg w/3' 0# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/- erf. 2nd stage - flush 2-7/8' 1#; 15 min SIP 4345#. Sell	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals "WL entry guide, "XN" nipple, tbg sub, nipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; ' KCl wtr; loaded ann & 13-3/8" csg (via 4900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959':	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FI 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top po Max P - 5600#; Min P - 5370#; AIR 2.3 bpm; ISIP 473 MCFPD; TP 70; 24/64" ck.	OTHER: <i>t details, and give pertinent dates,</i> <i>dn ann.</i> ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r <i>e, seal assy & 4" J-latch lo</i> on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Per 11,200'. Loaded tbg w/3' 0# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/- erf. 2nd stage - flush 2-7/8' 1#; 15 min SIP 4345#. Sell <i>e and belief.</i>	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; '6 KCl wtr; loaded ann & 13-3/8" csg (via 1900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959'; ing to plant 5/1/97. 5/10/97 prod: 121	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FI 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top pr Max P - 5600#; Min P - 5370#; AIR 2.3 bpm; ISIP 473 MCFPD; TP 70; 24/64" ck.	OTHER: <i>t details, and give pertinent dates,</i> <i>dn ann.</i> ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r <i>e, seal assy & 4" J-latch lo</i> on tbg. Instl'd wrap-aroun L dn tbg, surf - 3700'. Per 11,200'. Loaded tbg w/3' 0# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/- erf. 2nd stage - flush 2-7/8' 1#; 15 min SIP 4345#. Sell	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; '6 KCl wtr; loaded ann & 13-3/8" csg (via 1900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959'; ing to plant 5/1/97. 5/10/97 prod: 121	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FI 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top pr Max P - 5600#; Min P - 5370#; AIR 2.3 bpm; ISIP 473 MCFPD; TP 70; 24/64" ck.	OTHER: t details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo pon tbg. Instl'd wrap-around L dn tbg, surf - 3700'. Pert 11,200'. Loaded tbg w/39 D# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/ erf. 2nd stage - flush 2-7/8' 1#; 15 min SIP 4345#. Sell c and belief. TITLE Regulatory	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; '6 KCl wtr; loaded ann & 13-3/8" csg (via 1900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959'; ing to plant 5/1/97. 5/10/97 prod: 121	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" ::ipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FJ 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top per Max P - 5600#; Min P - 5370#; AIR 2.3 bpm; ISIP 473 MCFPD; TP 70; 24/64" ck. Thereby certify that the information above is true and complete to the best of my knowledg SIGNATURE	OTHER: t details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo pon tbg. Instl'd wrap-around L dn tbg, surf - 3700'. Pert 11,200'. Loaded tbg w/39 D# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/ erf. 2nd stage - flush 2-7/8' 1#; 15 min SIP 4345#. Sell c and belief. TITLE Regulatory	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; ' KCl wtr; loaded ann & 13-3/8" csg (via 4900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959'; ing to plant 5/1/97. 5/10/97 prod: 121 // Analyst DATE 5/21/97	: 6 ir g; & 1
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinen work) SEE RULE 1103. 4/15/97, bled off csg/tbg, pmp'd 4 BW dn tbg, 300 BW cut tbg @14,265'. POH w/ 2-7/8" tbg & 8 GLV's to 30 4-1/8" DC's on 431 jts 2-7/8" tbg to 13,714' TOL. Set surf - 6009' (600#); pkr @8211', tst'd 7" lnr 8211' - 13 pkr @13,660', tst'd CIBP @13,708' to 3000#. Circ'd defoam; spot'd 350 gals 10% acid 12,735'-966'. POH "X" nipple, 5-1/2" mill-out ext & 7" BWB pkr on WL; re-entry guide btm'd @12,756'. RIH w/muleshoe guid tbg to 7500#. ND BOP; spaced out, instl'd 10M# tree of Landed tree; NU 11"10M flange; flowline & swab'd FI 12,090'-915' & 12,948'-959'. Swabd - SFL 3000'; FFL ann) w/50 BW. Press'd to 500#; PIR w/0.5 bpm @490 surf; FFL 4500'. RU 1-1/4" CT & acid pmps. Acidize @12,959'; flushed acid dn 2-7/8" x 1-1/4" ann to top pr Max P - 5600#; Min P - 5370#; AIR 2.3 bpm; ISIP 473 MCFPD; TP 70; 24/64" ck. 1 hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE MALL.	OTHER: t details, and give pertinent dates, dn ann. ND 11"10M WHI 170'. Dmp'd 35' "H" cmt 1 CIPB @13,708', RIH w/7" 709' CIBP to 700#; loaded hole, w/pkr @12,966' w'/2' to 12,714', RIH with 4-1/2' pkr @12,725' (top), "X" r e, seal assy & 4" J-latch lo pon tbg. Instl'd wrap-around L dn tbg, surf - 3700'. Pert 11,200'. Loaded tbg w/39 D# w/3% KCl wtr. ISITP 4 d w/3000 gals 15% HCl w/ erf. 2nd stage - flush 2-7/8' 1#; 15 min SIP 4345#. Sell c and belief. TITLE Regulatory	including estimated date of starting any proposed F & tree/NU 5M# BOP. Ran freept, RIH 14,230'-265' in 4-1/2" lnr. RIH w/6" bit & pkr & SN on tbg; pkr @6009', tst'd 7" ln ann, pkr @8211, PIR w/3 bpm @150# - s 75 gals R-2264, 25 gals clay stab, 10 gals 'WL entry guide, "XN" nipple, tbg sub, hipple @12,744', "XN" nipple @#12,755' & c sub on 404 jts 2-7/8" tbg to 12,711'; tst'c td in WH; latched into pkr @12,725'. I'd Morrow "A" & "B": 12,838'-846'; ' KCl wtr; loaded ann & 13-3/8" csg (via 4900#; 5 min 4450#. Swab'd perfs: SFL- 40% meth; 1st stage: 1500 gals dn CT " tbg w/1500 gals w/3% KCl to 12,959'; ing to plant 5/1/97. 5/10/97 prod: 121 // Analyst DATE 5/21/97	: 6 ir g; & 1

