

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

COPY TO O. C. C.

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

AH Blinebry Fed. NCT-1

9. WELL NO.

23

10. FIELD AND POOL, OR WILDCAT

Blinebry Drinkard, Tubb

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 29 T-22-S, R-38-E

12. COUNTY OR PARISH

Lea

13. STATE

NM

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

Box 728 Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

660' FWL & 1980' FWL of Sec. 29, T-22-S, R-38-E,
Unit letter C.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3381'-OR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) Downhole Commingle

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull rds & pmp from Blinebry & Drinkard strings.
2. Perf. w/4 JSPP in Blinebry & Drinkard csq. 6855-6860 & 6833-6888 to establish comm. between csqs.
3. Magnetically orient into the formation & perf. 6152, 6158, 6166, 6172, 6177, 6183, 6190, 6199, 6206, 6221, 6224, 6253, 6256, 6260, 6266.
4. Run RBP to 6300. Set pkr @ 6100 on 1 1/2" tbq.
5. Acidize Tubb perms 6152-6266' w/6000 gals 15% NEA in 3 stgs. w/100-200 lbs. Benzoic acid flakes between stgs.
6. Pull pkr & RBP.
7. Run retrievable seating nipple in Drinkard csq.
8. Run rds & pmp in Drinkard csq.
9. Test & place on prod. w/Blinebry, Tubb & Drinkard zones downhole commingled.

Approved by NMOCC Case #5278
Order #R-4837

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. Dist. Supt.

DATE August 26, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

RECEIVED
OCT 1 1972
OIL CONSERVATION DIVISION
BUREAU OF LAND MANAGEMENT