

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

~~LC 03100~~ **LC 032100**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. **LOCKHART CH**
FEDERAL NCT-1 #10

9. API Well No.

30-005-21104

10. Field and Pool, or Exploratory Area

BRUNSON, DRINKARD-ABO-SOUT

11. County or Parish, State

LEA, NEW MEXICO

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

TEXACO EXPLORATION & PROD.

3. Address and Telephone No

P. O. BOX 3109, MIDLAND, TX 79702 (915) 688-4492

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT LETTER H 1980' FNL & 660' FEL
SEC 18 T-22S R-38E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) Notify BLM of intent to plug and abandon well
- 2) M.I.R.U., Nipple down wellhead, Nipple up B.O.P. Note: this is a slim hole completion W/ 2-7/8" tubing as casing.
- 3) T.I.H. W/workstring to @ 6400'. Circ wellbore W/25# per bbl. salt gel mud
- 4) Spot 25 sx cmt, plug from 6267-5517 (Tubbs-Blindbry)
- 5) Spot 25 sx cmt, plug from 5285-4535 (Glorieta)
- 6) Spot 25 sx cmt, plug from 4102-3352 (San Andres)
- 7) Spot 25 sx cmt, plug from 2705-1955 (Yates - B. Salt)
- 8) SPot 25 sx cmt, plug from 1454-704 (T-Salt 7-5/8" shoe plug)
- 9) Spot 10 sx cmt, plug from 300' - Surface
- 10) Cut off wellhead; install dry hole marker; clean off location; rig down and move off

14. I hereby certify that the foregoing is true and correct

Signed David W. Glass

Title Petroleum Engineer

Date 5/15/97

(This space for Federal or State office use)

(OFFIC. SCD.) **DAVID R. GLASS**

PETROLEUM ENGINEER

Approved by

Conditions of approval, if any:

Title

Date MAY 19 1997

SEE ATTACHED FOR

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

C.H. COOK ART (NCT-1) #10

KDD
10

GROUND LEVEL

EL. 1 - 3376'

10 SX - 300' - SURFACE

9 7/8" HOLE

7 5/8" 24" H-40 CSQ SET @ 1350'

600 SX - CMT. C.A.L.

6 3/4" HOLE

25 - 1454 - 704

Anhydrite	1330'
Top of Salt	1414'
Base of Salt	2510'
Yates	2705'
San Andres	4102'
Glorieta	5285'
Blinberry	5705'
Tubb	6267'
Drinkard	6598'

25 SX - 2705 - 1955 (Yates - B.S.)

25 SX 4102 - 3352 (SAN ANDRES)

25 SX - 5285 - 4535 (Glorieta)

25 SX 6267 - 5517 (Tubb) blini

18 PE 6436' w/ 35' of CMT.

UPPER DRINKARD ZONE

18 PE 6775'

DRINKARD ZONE

2 7/8" 6.5" J-55 CSQ SET @ 7247'

800 SX - TOP CMT @ SURFACE (71% FILL)

PE 6514, 6519, 6533,
6543, 6562, 6577, 6597, 6609,
6637, 6666, 6673,
6691, 6701, 6710 (15 PE)

PE 7020, 7098, 7103, 7110, 7120,
7130 (18 PE)

PATD.
7236

"Slim Hole"

F.M.R.

6-24-76