

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-21197
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 005502
7. Lease Name or Unit Agreement Name McCallister
8. Well No. 1
9. Pool name or Wildcat Paddock

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Kelton Operating Corporation	
3. Address of Operator P.O. Box 276, Andrews, Texas 79714-0276	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>7</u> Township <u>22S</u> Range <u>38E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3342' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- 5-31-94 Pull rods and tubing. Run Bridge plug and set at 5518'. Test to 500#. Held good. Dump sand on plug.
  - 6-01-94 Perforate at 5410-16, 5420-28, 5433-36, 5450-56, 5462-67, 5478-82:38 holes. Acidize with 4000 gallons 15% NeFe acid. Swabbed back acid residue. SION.
  - 6-02-94 SITP-110#. Swabbed load back. 10% oil cut with gas. SION. Set up frac.
  - 6-03-94 SITP-170#. RU to frac with 36,000 gallons 50/50 CO2 and 70,000# sand. Shut in for 4 hours and flow well back.
  - 6-04-94 FTP- 20#. RU to swab. Recovering load. Left open overnight to tank.
  - 6-04-94 LD workstring. TIH with tubing rods and pump. PBTD - 5518'. Clean up and test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. Dale Kelton TITLE President DATE 6-9-94  
TYPE OR PRINT NAME TELEPHONE NO. 915-524-6400

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

JUN 14 1994

2A Bluebird, 540

RECEIVED

JUN 10 1994

LOS ANGELES  
OFFICE