

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-21274
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-934
7. Lease Name or Unit Agreement Name NEW MEXICO "M" STATE
8. Well No. 47
9. Pool name or Wildcat LANGLIE MATTIX

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WATER INJECTION
2. Name of Operator GP II ENERGY, INC.
3. Address of Operator PO BOX 50682 MIDLAND, TEXAS 79710

4. Well Location Unit Letter "N" : 660 Feet From The South Line and 2310 Feet From The West Line Section 20 Township 22-S Range 37-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3380' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

GP II PLANS TO START PLUGGING PROCEDURES ON THIS WELL WITHIN THE NEXT 60 DAYS.

1. MOVE IN AND RIG UP
2. SET CIBP @ 3394' (100' above perfs @ 3494' - 3529')
3. PERFORATE 2-7/8" TUBING/CASING @ 2440' AND SET 25 sxs CEMENT PLUG - TAG
4. PERFORATE 2-7/8" TUBING/CASING @ 1100' AND SET 25 sxs CEMENT PLUG - TAG
5. SET PLUG AT 356' - 256' AND TAG (Surface Casing @ 306')
6. SET 60' PLUG AT SURFACE
7. CLEAN LOCATION AND MOVE OFF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tonya Garza TITLE Production Analyst DATE 03-27-2001

TYPE OR PRINT NAME TONYA GARZA TELEPHONE NO. 915-684-4748

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL FILED IN
FILED IN
THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF DRILLING OPERATIONS FOR THE COMPLETION OF ANY WELL.