

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Cons. Division

P.O. Box 1980

Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P Inc.

3. Address and Telephone No.

P.O. Box 3109 Midland, Texas 79702 (915) 688-4492

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FNL 198 FEL Sec 29 T22S R38E Unit Letter B

5. Lease Designation and Serial No.

41655

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

A.H. Blinbry Fed NCT-1#

9. API Well No.

30-025-21404

10. Field and Pool, or Exploratory Area

Blinbry, Drinkard

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Notify BLM of intent to plug

2. MIRU on Y string NU BOP

3. Retrieve SN @ 5696' Set CIBP @ 6750 w/20' cement

4. NU BOP on Z string

5. Set 2 7/8" CIBP @ 6130 w/20' cement

6. RIH circulate hole w/9.8# mud (Z&Y string-hole@5831-5346)

7. 25 sx cement 5850-5530 WOC/tag

8. 10 sx cement 5200-5100

9. POH NU on Y string RIH tag plug @ 5530'

10. 10 sx cement 5200-5100

11. Cut and pull 2 7/8" @ 4500± (Y&Z)

12. 35 sx cement 2600-2500 WOC/tag (Yates)

13. 50 sx cement 1450-1350 WOC/tag (salt/shoe)

14. 35 sx cement 1260 1160

15. 10 sx cement 30' to surface

16. RDMO, cut off well head, install dry hole marker, clean location.

Y-Drinkard
Z-Blinbry

BUREAU OF LAND MGMT.
HOBBS, NEW MEXICO

1998 MAY -4 P 2:47

RECEIVED

14. I hereby certify that the foregoing is true and correct

Signed

(This space for Federal or State office use)

Title Reservoir Engineer

Date 4/28/98

Approved by

COND. SEC. GARY GOURLEY

Title PETROLEUM ENGINEER

Date

MAY 14 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations in any manner within its jurisdiction.

*See instruction on Reverse Side