

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIP DATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0356435

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "L"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Triste Draw Delaware

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 34, T-23S, R-32E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Union Oil Company of California

3. ADDRESS OF OPERATOR

P.O. Box 671 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

330' FSL & 330' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3627' KDB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

TD: 5039' FBTD: 5001' PERFS: 4961 - 4965'

CASING RECORD: 8-5/8" @ 811' w/325 sx; 5 1/2" @ 5036' w/225 sx

PROPOSED PLUGGING PROCEDURE:

Set 50 sx plug 5001 - 4686'

Cut & pull 5 1/2" casing from free point (1500' est.)

Set 50 sx plug across 5 1/2" casing stub

Set 50 sx plug across 8-5/8" surface casing 861 - 761'

Set 10 sx plug 32' - surface

Cut off well head, weld 1/2" steel plate on surface casing & install dry hole marker

Clean up location & abandon

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Drilling Supt.

DATE April 24, 1973

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side