

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instruction on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-033706-b

6. IF INDIAN, ALLOTTED OR TRIBE NAME

NONE

7. UNIT AGREEMENT NAME

NONE

8. FARM OR LEASE NAME

C. P. Falby "b"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Eumont

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 8, T-22-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR TEXACO Inc.	
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  Well located 660' from the West Line, and 660' from the South Line of Section 8, T-22-S, R-37-E, Lea County, N. M.	
14. PERMIT NO. Regular	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3415' (D. F.)

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We propose to abandon the Penrose Skelly zone temporarily as follows:

1. Set Sweet Hookwall Packer at 3606', with blank off nipple above packer.
2. Penrose Skelly zone abandoned as of November 18, 1963, only the Eumont oil zone to be producing.
3. Test Eumont Oil zone, place well on production.

Subject to: Setting of a blanked off packer does not constitute permanent abandonment of the Penrose Skelly zone. If at the time the well is permanently abandoned and conditions so warrant, all perforations in the lower portion of the hole must be cemented before any nipple cement plugs are set.

18. I hereby certify that the foregoing is true and correct

SIGNED

H. D. Raymond

TITLE

Assistant District  
Superintendent

DATE February 10, 1965.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:


TITLE

APPROVED

FEB 10 1965

\*See Instructions on Reverse Side

J. L. GORDON  
ACTING DISTRICT ENGINEER



TEXACO Inc.  
 DIAGRAMMATIC SKETCH  
 C. P. Falby "b" Well No. 3  
 Lea County, New Mexico  
 2-9-65