Submit 3 Copies to Appropriate District Office

State of New Mexico ergy, Minerals and Natural Resources Departm

Form C-103 Revised 1-1-89

<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

DISTRICT II

Santa Fe, New Mexico 87504-2088

WELL API NO.		
5. Indicate Type of L	ease	
	STATE	FEE X

P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE FEE X		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERI	OR PLUG BACK TO A 7 Lace Name of Unit Agreement Name		
(FORM C-101) FOR SUCH PROPOSALS.)	Lou Wortham "B"		
1. Type of Well: On. GAS WELL WELL OTHER			
2 Name of Operator Anadarko Petroleum Corporation	8. Well No. 1		
3. Address of Operator P.O. Box 806 Eunice, NM 88231	9. Pool name or Wildcat Penrose-Skelly Grayburg		
4. Well Location			
Unit Letter B: 660 Feet From The North	Line and Feet From The Line		
Section 11 Township 22S Ran			
10. Elevation (Show whether D 3356 GR	F, RKB, RT, GR, etc.)		
11. Check Appropriate Box to Indicate N	ature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF		
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WOFIK ALTERING CASING		
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING CASING TEST AND CEMENT JOB			
OTHER:	OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.	give pertinent dates, including estimated date of starting any proposed		
1. MIRUPU TOH w/ rods & pump, lower tbg to check for fill & TOH w/			
Prod. tbg. 2. If substantial fill indicated, RU reverse unit & CO w/ 4 3/4" bit to 3818' (anticipate @ 52' of fill according to csg repair 11-8-83			
showing clean out to 3766'). 3. TIH w/ 5' treating PKR on 2 3/8 tbg. Set PKR @ 3420' (acidized 11-8-83 & communicated between 3612 & upper perfs @ 3550').			
4. Treat perfs 3649-58, 3678-84, 369 3767-72, 3786-94 (Grayburg) & 351 w/3000 gal 15% NEFE, Drop deverte	1-96, 3/(2-06, 3/18-21, 3/49-60, 9-24, 3529-35, 3540-50 (Penrose) r (1000# rock salt) Pump 2400		
gal 15% NEFE, overflush 50 B/2% K 5. TOH w/ PKR. TIH w/ prod tbg, pum	p, & rods. Return to production.		
6. Conduct production test.			
I hereby certify that the information above is true and complete to the best of my knowledge and b	Field Foreman 10-31-90		
SIGNATURE SULL STORY Ly TITL	I I CI G I CI C		
TYPE OR PRINT NAME	TELEPHONE NO.		
(This space for State Use)	NOV 0 2 1990		

_ TILE -

APPROVED BY ---

NOV 0 2 1990