N.M. GIE CONS. COMMISSION P.O. BOX 1980 HORSE WEW MEXICO AROAD

Form 3160-5

UNITED STATES

FORM APPROVED

(June 1990)		OF LAND MANAGEMENT			Budget Bureau No. 1004-0135 Expires: March 31, 1993		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.					Lease Designation and Serial No. LC 032104 If Indian, Alottee or Tribe Name		
	Use "APPLICATION	FOR PERMIT —" fo	or such proposals				
SUBMIT IN TRIPLICATE					7. If Unit or CA, Agreement Designation		
1. Type of Well: GAS WELL OTHER					8. Well Name and Number BLINEBRY A. H. FED NCT-1		
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.					37		
3. Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0426					9. API Well No.		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter A: 660 Feet From The NORTH Line and 990 Feet From The					30 025 21838 10. Field and Pool, Exploaratory Area DRINKARD		
	ection 20	Township 22S	Range			r Parish, State LEA , NEW	/ MEXICO
12. Ch	eck Appropriate	Box(s) To Ind	dicate Nature				
Notice of Intent Subsequent Repo	ort		Abandonment Recompletion Plugging Back Casing Repair Atlering Casing OTHER:	EXTEND TA STATU		Change of Plant New Construction Non-Routine Fra Water Shut-Off Conversion to Ir Dispose Water (Note: Report results of multip Completion R	on acturing ajection
 Describe Proposed or Cowork. If well is direction Texaco Exploration and Proposed or Cowork. Texaco Exploration and Proposed or Exploration and Proposed or Exploration and Proposed or Exploration Notify BLM 24 hours in 	roduction Inc. respectfu ded TA status for the all lbsequent 3160-5 will b	illy submits it's plans	easured and true vs concerning notic	vertical depths for all e 0162 (067A).	markers and z	ones pertinent to this	ıy proposed s work,)*.
Test casing and plug w Classify well to TA state Temporarily Abandonm	us. TEPI will submit pr	essure chart and su	bsequent report r	equesting			RECEIVED
14. I hereby certify that the foregoing	is true and goingst	TITLE	Engineerin	g Assistant		DATE	10/27/94
CONDITIONS OF APPROVA	SGD.) JOE G. L., IF ANY: Second Kes it a crime for any person in	attachel	Test to	LEUM ENVIOL	ermed	DATE 11/2	9/94 days.
representations as to any matter v	within its jurisdiction.		,	= = gone; or are ornited	Ciacos any laise,	incurvous or traudulent stat	ements or

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, "No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.