	• • •		(P_{i})
NO. OF COPIES RECEIVED			Form C-103 Supersedes Old
DISTRIBUTION			C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSE	ERVATION COMMISSION	Effective 1-1-65
FILE			
U.S.G.S.			Sa. Indicate Type of Lease
LAND OFFICE			
OPERATOR	J		5. State Oil & Gas Lease No. E-3480-1
(DO NOT USE THIS FORM FOR PRO	RY NOTICES AND REPORTS ON PLUG BA	WELLS Ack to a different reservoir. H proposals.)	
Die Arreitat			7. Unit Agreement Name
OIL X GAS WELL	OTHER-		
2. Name of Operator			8. Farm or Lease Name
Gulf Oil Corporation			R. E. Cole (NCT-A)
3. Address of Operator			9. Well No.
Box 670, Hobbs, New Mexico 88240			8
4. Location of Well			10. Field and Pool, or Wildcat
К 2	2130 FEET FROM THE South	LINE AND FEET FROM	Cary Montoya
			$\mathbf{\mathcal{A}}$
West use sect	10N 16 TOWNSHIP 22-S	RANGE 37-E	
THE CINE, SECT	15. Elevation (Show whether i		
	12. County		
	3	392' GL	Lea AIIIIIIII
16. Check	Appropriate Box To Indicate N	ature of Notice, Report or Ot	her Data
	NTENTION TO:		T REPORT OF:
			_
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER Abandoned So. MC	Cormack Silurian and
OTHER			in Come Manhana
	presentions (Clearly state all pertinent deta	attempted to complete	an UATY MONFOYA

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7295' PB, 7302' TD.

Pulled producing equipment. Squeezed Silurian perforations 7186' to 7210' with 150 sacks of Class C cement at 3,000% pressure. Cleaned out to 7295'. Perforated 7" casing in Montoya zone with 4, 1/2" JHPF at 7284-86' and 7255-57'. Ran treating equipment and treated new perforations with 2,000 gallons of 20% NE acid. Pulled treating equipment. Ran 2-3/8" tubing and set at 7270'. Ran rods and pump. Pumped well approximately two weeks with no indication of commercial production.

Plans have been made to abandon Montoya and complete in Drinkard as follows: Pull producing equipment. Set CI BP at 7220' and cap with 10' cement, abandoning Montoya perforations 7255' to 7286'. Test casing and BP with 500#. Set CI BP at 6655' and cap with 10' cement. Perforate Drinkard zone in 7" casing in the approximate interval 6382' to 6567'. Run treating equipment and treat new perforations with 2,000 gallons of 15% NE acid and frac with 10,000 gallons of gel brine and 25,000 gallons containing 1 to 2# SPG. Flush with 2,000 gallons of gel water. Pull treating equipment. Run 2-3/8" tubing. Swab and clean up and return well to production.

18. I hereby certify that the information above is true and comple		TITLE Area Engineer	DATE July 3, 1974	
	Orig. Signed by			
ONDITIONS OF APPROV	Joe D. Ramey Dist. I, Supv.	TITUE	DATE	