STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| 48. 87 COPIES RECEIVED | |
|------------------------|------|
| DISTRIBUTION | |
| SANTA FE | |
| PILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | ĺ |

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

Revised 10-1-78 SANTA FE, NEW MEXICO 87501 5a. Indicate Type of Leuse State X 5. State Oli 6 Gas Lease No. B-3480-1 SUNDRY NOTICES AND REPORTS ON WELLS

[DO NOT USE THIS FORM FOR PROPOSALS TO CRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.

USE "APPLICATION FOR PERMIT _" IFORM C-1011 FOR SUCH PROPOSALS.! Dua1 OTHER. 8. Form or Lease Name 2. Name of Operator R. E. Cole (NCT-A Gulf Oil Corporation 3. Address of Operator P. O. Box 670, Hobbs, NM 88240 10. Field and Pool, or Wildcat 14. Location of Well Drinkard & Blinebry 1980 FEET FROM THE SOUTH LINE AND 1980 UNIT LETTER ___ RANGE __37E 22S 16 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3394 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PLUG AND ABANDON FORM REMEDIAL WORK PLUG AND ABANDONMENT TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CABING Acidizing

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Pump 1000 gals 15% NEFE double inhibited acid &55 sacks AE-122 at 6600'. Pump 1000 gals 15% NEFE double inhibited acid with AE-122 at 5750'. GIH with tubing to 6900'. GIH with pump and rods. Test before work, 8 BO, 70 BW with 75 MCF gas. Now pumping 40 BO, 0 BW with 130 MCF gas. Complete after acidizing Blinebry & Drinkard 2-22-82.

| Arga Engineer $3=18=82$ | PDD'+ | | • | | 3-18-82 | |
|----------------------------|--------|-------|---------------|------|---------|--|
| Area Engineer DAYE 3-18-82 | RDPite | TITLE | Area Engineer | DAYE | 3-18-82 | |