| NO. OF COPHIS FICEIVED DISTRIBUTION SANTA FE | NEW MEXICO OIL CONSERVATION COMMISSION | Form C-103 Supersodes Old C-102 and C-103 Effective 1-1-65 | |
|---|--|---|------------|
| 0.5.0.5. | -1 | Sa. Indicate Type of Lessa | i i i i |
| OPERATOR | | State 5. State Oil & Gas Legge He. | XĄ |
| (DO NOT USE THE FORM FOR THE TAPPLICATION TO THE USE TAPPLICATION | RY NOTICES AND REPORTS ON WELLS DUDALS TO DRILL OF TO DEPLIN OR PLUG WARPOSALS.) HON FOR PERMIT - " FORM C-101) FOR SUCH MADPOSALS.) | 7. Unit Agreement House | <u> </u> |
| Gulf Oil Corporation | | 6. Fernior Leave Linne O. I. Boyd | |
| Box 670, Hobbs, New Me | xico 88240 | 9. Well No. | |
| 4. Location of Well Unit Letter, | 990 FEET FROM THE South LINE AND 1650 FEET FROM | 10. Field and Pord, or and P Drinkard | |
| THE East LINE, SECTI | ON 23 TOWNSHIP 22-S RANGE 37-E NMPM. | | |
| | 15. Elevation (Show whether DF, RT, GR, etc.) 3320' GL | 12. County Lea | |
| Check | Appropriate Box To Indicate Nature of Notice, Report or Oth TENTION TO: SUBSEQUENT | REPORT OF: | |
| PEFFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING Plug and Adamsonmen. | 1 <u>.</u> |
| OTHER Re-perforate 5-1/ | 2" casing and acidize | | • |

7. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and work) SEE RULE 1103.

7270' PB.

Plans have been made to re-perforate 5-1/2" casing as required by Mr. Leslie A. Clement's letter of August 25, 1975, as follows:

Pull producing equipment. Perforate 5-1/2" casing with 4, 1/2" JHPF at approximately 2,000'. (Top of cement behind 5-1/2" casing is at approximately 2100' as per temperature survey). Squeeze perforations at 2,000' with approximately 1350 sacks of Halliburton Light containing 18% salt, .6% Halad 22 and 1/4# flocele per sack and 350 sacks of Class C containing 18% salt salt, .6% Halad 22 and 2% Ca Cl2. If cement does not circulate, will run temperature survey. Will re-cement if flow or pressure is still detected on 5-1/2" - 9-5/8" annulus. WOC 24 hours. Clean out and test casing with 500#, 30 minutes. Run packer and 2-3/8" tubing. Set packer at approximately 6400'. Treat Drinkard perforations 6268' to 6464 with 3,000 gallons of 15% NE HCL acid. Flush with 8.6# brine water. Swab and clean up and return well to production.

16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| FIGNED D. F. Berlin | titte Area Engineer | DATE November , 1975 |
|---------------------|---------------------|----------------------|
| | | NO: 4 |
| APPROYLD DY | TITLE | DATE |
| | | |

CONDITIONS OF APPROVAL, IF ANY:

Ν