NO. OF COMIS PECSIVID	Form C-103 Supersedex Old		
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103	
SANTATE	Effective 1-1-65		
FILC			
U.S.G.S.		Sa. Indicute Type of Leaso Statu Fee X	
LAND OFFICE			
OPERATOR		5. State Off & Gan Lease No.	
		- CULLECCO CONTRACT	
SUNDE			
LOO NOT USE THIS FORCE FOR HAR USE TRAFFLICAT	RY NOTICES AND REPORTS ON WELLS MUSACY TO CHARLE WITH TO PLATER OF THE A OFFICE CAT RESERVOID.	ATTHINN MARINE	
1.		7. Unit Agreenent Name	
	0THER.		
2. Name of Operator	6. Farm of Lease Name		
Gulf 0il Corporation	R. E. Cole (NCT-A)		
1. Aldress of Operator		9. Well No.	
Box 670, Hobbs, New Me	12		
4, Location of Well		10. Field and Fool, or Wildat	
D	Undes Abo		
UNIT LETTER	990 FEET FROM THE North LINE AND 330 FEET FROM		
West			
THELIRE, SLETT	ON 16 22-S RANGE 37-E NMPIN	<u> VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII</u>	
101000000000000000000000000000000000000	12. County		
	Lea		
16. Charles	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data	
		T REPORT OF:	
NOTICE OF IT	NTENTION TO: SUBSEQUEN		
[]		ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDOR REMEDIAL WORK	· · · · · · · · · · · · · · · · · · ·	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOD		
POLE ON ACTER CASING Land		-Commonly Critican	
	OTHER Abandoned So. M	cCormack_Silurian	
Abandon Cary Mont	oya and complete		
Abandon Cary Mont	OTHER Abandoned So. M	te in Cary Montoya	

7347' PB.

Pulled producing equipment. Squeezed Silurian perforations 7134' to 7260' with total of 250 sacks of Class C cement. WOC 18 hours. Cleaned out to 7347' and tested squeezed perforations with 500%, 30 minutes, OK. Perforated Cary Montoya zone in 5-1/2" casing with 4, 1/2" JHPF at 7307-09' and 7336-38'. Ran treating equipment and treated new perforations with 4500 gallons of 15% NE HCL acid. Swabbed water only.

Plans have now been made to abandon Cary Montoya zone and complete in Abo as follows: Set CI BP at approximately 7285' and cap with 35' cement. Set CI BP at approximately 7100'. Perforate 5-1/2" casing in the approximate interval 6772' to 7011' with 4, 1/2" JHPF. Run treating equipment and treat new perforations with 6000 gallons of 20% retarded HCL acid. Swab and clean up. Place well on production.

18, 1 hereby certify that t	the information above is true and con	mpicte to the best o	f my knowledge and belief.		,
SIGNED D.T.	Berlin	TITLE Are	ea Engineer	DATE Decemt	oer 21, 1976
	Crig. Signed by			DATE	T AR
CONDITIONS OF APPRO	DVAL, IF ANYI	TITLE			, 1

ECENTED ·· 211976 OL CONSERVATION COMM. HOBBS, N. M.

•