

NO. OF COPIES RECEIVED
DISTRIBUTION
SANTA FE
FILE
U.S.G.S.
LAND OFFICE
OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS	
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.	
1. OIL <input checked="" type="checkbox"/> WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Samedan Oil Corporation	8. Farm or Lease Name Boyd
3. Address of Operator c/o Hobbs Pipe & Supply Company, Box 2010, Hobbs, N. M.	9. Well No. 2
4. Location of Well UNIT LETTER <u>J</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>2090</u> FEET FROM THE <u>1650</u> LINE, SECTION <u>23</u> TOWNSHIP <u>22</u> RANGE <u>37</u> N.M.P.M.	10. Field and Pool, or Wildcat East Brunson-McKee
11. Elevation (Show whether DF, RT, GR, etc.) U.K.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Propose to spot a 25 sx cement plug across perforations.
2. Propose to spot a 25 sx cement plug at 4 1/2 casing stub at 4600'.
3. Propose to spot a 25 sx cement plug at base of salt.
4. Propose to spot a 25 sx cement plug at 9-5/8 casing shoe at 1159'.
5. Propose to spot a 10 sx cement plug at surface with marker.
6. Hole will be loaded with mud-laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Agent</u>	DATE <u>4/2/71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>APR 14 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 18 1971

OIL CONSERVATION COM.
ROOM 1. 11