

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Anadarko Production Company	8. Farm or Lease Name Hugh
3. Address of Operator P.O. Box 806 Eunice, New Mexico 88231	9. Well No. 12
4. Location of Well UNIT LETTER <u>C</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Penrose Skelly
15. Elevation (Show whether DF, RT, GR, etc.) 3355 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. RUPL. TOH w/rods, pump & 2-3/8" tbg.
2. TIH w/4-3/4" bit. Clean out scale & junk iron to TD 3893'.
3. TIH w/RBP & PKR. Set RBP @ 3880' & PKR @ 3800'. Acidize perfs 3812-76 w/1000 gal 15% NE HCL Acid @ 3 BPM @ 1300# PSI w/165 gal Scale Preventive (SP-181) and 5 gal Fludex OW-77 (surfactant) and 5 gal Demulsifier RP-2336 in 50 bbls produced wtr. Over flushed w/100 bbls wtr. ISIP 600# PSI. Reset BP @ 3800' & PKR @ 3650'. Acidize perfs 3679-3741 w/1000 gal 15% NE Acid & 165 gal (SP-181) & 5 gal Fludex OW-77 (Surfactant) & 5 gal RP-2336 (Demulsifier) in 50 bbl prod wtr & 100 bbl over flush @ 3 BPM @ 1600 # PSI w/a ISIP 850# PSI. Reset RBP @ 3650' & PKR @ 3512'. Acidize perfs 3541'-3632' w/1000 gal 15% NE Acid w/165 gal SP-181 & 5 gal Fludex OW-77 (Surfactant) & 5 gal (Demulsifier) RP-2336 w/50 bbl prod wtr & 100 bbl over flushed @ 3 BPM @ 2000# PSI w/ISIP 1500# PSI. Retrieve RBP & TOH.
4. TIH w/prod string. POP @ 3:00 P.M. 6-11-82. Prod before WO: 3 B/O, 4 B/W, 21.0 MCF Gas. Prod after WO: 3 B/O, 107 B/W, 15.2 MCF Gas w/1320 BLW.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by: [Signature] TITLE Production Foreman DATE July 9, 1982

APPROVED BY: [Signature] ORIGINAL SIGNED BY: [Signature] TITLE: [Signature] DATE: JUL 14 1982
CONDITIONS OF APPROVAL, IF ANY: [Signature]