

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Imperial-American Management Co.	8. Farm or Lease Name L. B. Jones
3. Address of Operator 507 Midland Savings Bldg., Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>West</u> LINE AND <u>1650</u> FEET FROM THE <u>South</u> LINE, SECTION <u>6</u> TOWNSHIP <u>22-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3346.6' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and Abandoned Well as follows:

8-25-71 Set Cast Iron Bridge Plug @ 6280' w/20' cement on top.

8-26-71 Loaded hole w/9.5# mud.
Shot off 7" casing @ 3199', pulled & laid down same.
Set 35 sx cement plug 2650-2750' (base of salt)
Set 35 sx cenebt okyg 1470-1570' (top of salt)
Set 50 sx cement plug 815-915' (base of 9-5/8")
Set 10 sx cement plug 0-20'.

Set Marker and cleaned up location - Ready for inspection 10-1-71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Carol K. Roney</u>	TITLE <u>Agent</u>	DATE <u>9-16-71</u>
APPROVED BY <u>Nathan E. Clegg</u>		TITLE <u>OIL & GAS INSPECTOR</u>
CONDITIONS OF APPROVAL, IF ANY:		DATE <u>DEC 1 1971</u>

RECEIVED

SEP 20 1971

OIL CONSERVATION COMM.
HOBBS, N. M.