

P+A ✓
TA ✓

PLUG & ABANDONMENT FORM

API NO. _____
OPERATOR ANADARKO PETRO. CORP.
LEASE NAME LM PSU '25'
WELL NO. 3
SEC. 28 TWP. 22 RANGE 37 UNIT B

Date plugging operations began - 8-18-97
Date plugging operations completed - 8-19-97
Name of plugging company - TRIPLE 'N'
Comments: _____

Signed By: Garry W. Hill
Date: 8-19-97

Anadarko Petroleum Corp.

Langlie-Mattix Penrose Sand Unit #25-3

Lea County, New Mexico

Job #2192

08-18-97 Monday

Notified Gary Wink w/ OCD of ML. MIRU Key rig. Did not have companion flange for wellhead. SI well and SDFN.

RT: 3:30-5:30 2.0 hrs CRT: 2.0 hrs

08-19-97 Tuesday

Notified OCD, Gary Wink, Buddy, & Charles. ND wellhead and NU BOP. RIH w/ 1 1/4" 2-3/8" workstring, tagged existing CIBP. RU cementer and circulated hole w/ mud, pumped 25 sx cmt 3491-3129'. POOH to 2497' and pumped 25 sx cmt 2497-2095'. POOH w/ tbgs. RU wireline and perforated @ 1250'. RIH w/ packer to 1197', established rate of 1.5 BPM @ 900 psi. POOH w/ packer, RIH w/ CICR and set @ 1197'. Squeezed 200 sx cmt under CICR, stung out and pumped 10 sx 1197-1052'. POOH w/ tbgs. RIH w/ wireline and perforated @ 440'. RIH w/ packer and established rate of 1.5 BPM @ 950 psi, no circulation to surface outside of 4-1/2" csg. Pumped 60 sx cmt 440' to surface. RD.

RT: 7:30-5:00 9.5 hrs CRT: 11.5 hrs