

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>NM-2A</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator <b>TEXAS PACIFIC OIL COMPANY, INC.</b>	8. Farm or Lease Name <b>State 'A' a/c-1</b>
3. Address of Operator <b>Post Office Box 1069 - Hobbs, New Mexico</b>	9. Well No. <b>111</b>
4. Location of Well UNIT LETTER <b>N</b> , <b>46'</b> FEET FROM THE <b>South</b> LINE AND <b>2173</b> FEET FROM THE <b>West</b> LINE, SECTION <b>4</b> TOWNSHIP <b>23-S</b> RANGE <b>36-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Jalmat/Langlie Mattix</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3496' GL</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Upon approval we completed the following:

1. Moved in, rigged up, installed BOP.
2. Drilled out to 4050', displaced mud with brine.
3. Logged well 2700-4232', top of cement 3090'.
4. Perforated 1-1/2" JSPF 3521' to 3710'.
5. Acidized w/3000 gallons, swabbed to flow.
6. Set CIBP at 3500', with 10' cement on top, perforated 3468-82'. Acidized with 1,500 gallons N.E. acid, swabbed and tested.
7. Well is now temporarily abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Sheldon Ward</u>	TITLE <u>Area Superintendent</u>	DATE <u>12-15-69</u>
APPROVED BY <u>Lester A. Clements</u>	TITLE <u>Oil &amp; Gas Inspector</u>	DATE <u>12-16-69</u>
CONDITIONS OF APPROVAL, IF ANY:		