

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL COMPANY, INC.	8. Name or Lease Name State "A" a/c-4
3. Address of Operator Post Office Box 1069 - Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER N 2173 FEET FROM THE WEST LINE AND 467 FEET FROM THE SOUTH LINE, SECTION 4 TOWNSHIP 23-S RANGE 36-E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3496' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval granted September 4, 1969 to plug and abandon above well as follows:

1. Rigged up, Ran tubing and spotted 25 sks cement at TD - 12,092'.
2. Filled hole with mud laden fluid between plugs as follows:
 - 25 sks spotted at 9327'
 - 25 sks spotted at 8168'
 - 25 sks spotted at 7712'
 - 25 sks spotted at 6980'
 - 25 sks spotted at 6150'
3. Set C.I.B.P. at 4240' with 3 sks cement on top.
4. Spotted 10 sks at surface and installed dry hole marker.
5. Cleared and cleaned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED Sheldon Ward TITLE Area Superintendent DATE 9-5-69

APPROVED BY [Signature] TITLE SUPERVISOR DATE

CONDITIONS OF APPROVAL, IF ANY: