

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-23275
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Hugh
8. Well No. 13
9. Pool name or Wildcat Eunice South (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Anadarko Petroleum Corporation	
3. Address of Operator P. O. Box 2497, Midland, TX 79702	
4. Well Location Unit Letter <u>D</u> : <u>330</u> Feet From The <u>North</u> Line and <u>820</u> Feet From The <u>West</u> Line Section <u>14</u> Township <u>22S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3348' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ <sup>v</sup>  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Isolate potential casing leak using packer & RBP.
2. Squeeze potential casing leak with cement, slurry vol & type determined from pump-in test.
3. Drill out cement and test.
4. Clean out fill 4105-4280.
5. Acidize 4137-4157 w/1500 gal NEFE + RS.
6. Acidize 4200-4280 w/2400 gal NEFE + RS.
7. POP.
8. Plan to start work as soon as possible.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard Williams TITLE Production Engineer DATE 7/15/98

TYPE OR PRINT NAME Richard Williams

TELEPHONE NO. 915-683-055

(This space for State Use)

ORIGINAL SIGNED BY CHRIS J. LAMAR

DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 7/28/1998

CONDITIONS OF APPROVAL, IF ANY: