TIVIES ANTIVE TIVIES ANTIVE TIVIES ANTION MEXICO OIL CONSERVATION COMMISSION FILE	Loom (* + 10) Supercodes ()]d G-102 and (-103 Effective 1-1-65
U.S.G.S. LAND OFFICE	Sa. Indicate Type of Lease State Peo X S. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS     IND NOT USE INTS CONTRACT TO PORT OF THE LOS AND REPORTS ON WELLS	7, Unit Agreement Name
2. Nome of Operator Cities Service Oil Company	8, Furm or Lease Hume
3. Address of Operator	Brunson-C 9. Wall No.
P. 0. Box 1919 - Midland, Texas 79701	12
4. Location of Well UNIT LETTER I 1980 South Line and 810 FEET FROM THE	10. Field and Pool, or Wildcat Penrose Skelly
East Bance 3 TOWNSHIP 22-S RANGE 37-E MMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 33821 GR	12. County Lea
16. Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
	REPORT OF:
PERFORM HEMEDIAL WORK       PLUC AND ARANDON       REVENTIONAL WORK         TEMPORABILY ARANDON       E         PULL OR ALTER CASING       E         OTHER       CHANGE PLANS	
<ul> <li>work) see NOLE 1103.</li> <li>T.D. 4350', P.B.T.D. 4311' - Grayburg. Following is the cement squee annulus pressure.</li> <li>1. MIRU pulling unit and pulled rods and tubing.</li> <li>2. Set HOWCO RBP at 3011'. Spot 15' sand on RBP.</li> <li>3. Perf. 4 cementing holes at 2651'.</li> </ul>	
<ul> <li>4. Set HOWCO SV EZ drill retainer at 2450'. Tested casing to 1000 to 1000#-ok.</li> <li>5. Cemented with 1225 sacks HOWCO Lite with 13# salt (16%) per sac with 5# salt (10%) per sack. Circ. 50 sacks to pit. Squeezed Max. press. 1000#. Reversed out 6 sacks.</li> <li>6. Drilled out cement retainer at 2450' and cement to 2565'.</li> <li>7. Tested to 1000# for 30 minutes - ok.</li> <li>8. Washed sand off RBP.</li> </ul>	k and 200 sacks Class C 170 sacks into formation
<ul> <li>9. Spotted 2500 gallons 15% acid 3530'-3780'. Set packer at 3533' gallons 15% LST Ne acid with additives.</li> <li>10. Pulled Packer and ran tubing, pump and rode.</li> <li>11. Put well on production.</li> </ul>	. Acidized with 2250
18.1 hereby certify that the information above is true and complete to the best of my knowledge and bellef.	
sience Region Oper. Manager	12-10-76
APPROVED BY LAYRING TITLE	DATE
CONDITIONS OF AFPROVAK, IF ANY	

	Etim C-103 Supersedes Old
IT FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	Effective 1-1-65
U.S.G.S.	5a. Indicate Type of Lease
	State Fee
OPERATOR	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESURVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
I. OIL GAS OTHER-	7. Unit Agreement Name
2. Name of Operator Cities Service Oil Company	8, Farm or Lease Name
3. Address of Operator P. O. Box 1919, Midland, Texas 79701	Brunson-C 9. Well No.
4, Location of Weil	12 10. Field and Pool, or Wildcat
UNIT LETTER I 1980 FEET FROM THE South LINE AND 810 FEET FROM	Democra (1 11
THE East LINE, BECTION TOWNSHIP 22S RANGE 37E	
15. Elevation (Show whether DF, RT, CR, etc.)	12. County
16	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO:	her Data T REPORT OF:
PERFORM REMEDIAL WORK	
	ALTERING CASING
COMMENCE DRILLING OPINS.	PLUG AND ABANDONMENT
Coment squeeze to shut off enging	
OTHER ANNULUS pressure.	
THER AITIMUUS FIESSURE. X 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any propo
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. is proposed to shut off casing annulus pressure in our Brunson-C #12 as	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103. is proposed to shut off casing annulus pressure in our Brunson-C #12 as 1. MIRU pulling unit - Kill well - Install BOP.	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103. is proposed to shut off casing annulus pressure in our Brunson-C #12 as 1. MIRU pulling unit - Kill well - Install BOP. 2. Pull rods and pump - pull tubing.	
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> </ul>	
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performance.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>is proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed.</li> <li>6. Pump into perforations and establish circulation.</li> <li>7. Squeeze 5 1/2" x 8 5/8" annulus.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed.</li> <li>6. Pump into perforations and establish circulation.</li> <li>7. Squeeze 5 1/2" x 8 5/8" annulus.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed.</li> <li>6. Pump into perforations and establish circulation.</li> <li>7. Squeeze 5 1/2" x 8 5/8" annulus.</li> <li>*</li> <li>8. RU reverse equipment. Drill out cement.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed.</li> <li>6. Pump into perforations and establish circulation.</li> <li>7. Squeeze 5 1/2" x 8 5/8" annulus.</li> <li>*</li> <li>8. RU reverse equipment. Drill out cement.</li> <li>9. Test casing.</li> <li>0. Release POOH w/RBP.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) set RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed and establish circulation.</li> <li>7. Squeeze 5 1/2" x 8 5/8" annulus.</li> <li>8. RU reverse equipment. Drill out cement.</li> <li>9. Test casing.</li> <li>0. Release POOH w/RBP.</li> <li>1. RIH w/treating packer on 2 3/8" EUE tubing.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed.</li> <li>6. Pump into perforations and establish circulation.</li> <li>7. Squeeze 5 1/2" x 8 5/8" annulus.</li> <li>*</li> <li>8. RU reverse equipment. Drill out cement.</li> <li>9. Test casing.</li> <li>0. Release POOH w/RBP.</li> <li>1. RIH w/treating packer on 2 3/8" EUE tubing.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed.</li> <li>6. Pump into perforations and establish circulation.</li> <li>7. Squeeze 5 1/2" x 8 5/8" annulus.</li> <li>*</li> <li>8. RU reverse equipment. Drill out cement.</li> <li>9. Test casing.</li> <li>0. Release POOH w/RBP.</li> <li>1. RIH w/treating packer on 2 3/8" EUE tubing.</li> <li>3. Swab until load is recovered.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18 proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed.</li> <li>6. Pump into perforations and establish circulation.</li> <li>7. Squeeze 5 1/2" x 8 5/8" annulus.</li> <li>*</li> <li>8. RU reverse equipment. Drill out cement.</li> <li>9. Test casing.</li> <li>0. Release POOH w/RBP.</li> <li>1. RIH w/treating packer on 2 3/8" EUE tubing.</li> <li>3. Swab until load is recovered.</li> </ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed on the performance of the p</li></ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed on the performance of the p</li></ul>	follows:
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 163.</li> <li>18. proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed on the performance of t</li></ul>	follows: ations.
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, including work) SEE RULE 1103.</li> <li>18. proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed on the performance of the performance of</li></ul>	follows: ations.
<ul> <li>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 163.</li> <li>18. proposed to shut off casing annulus pressure in our Brunson-C #12 as</li> <li>1. MIRU pulling unit - Kill well - Install BOP.</li> <li>2. Pull rods and pump - pull tubing.</li> <li>3. Set RBP @2661'. Dump sand on top of RBP.</li> <li>4. Perforate 5 1/2" casing at approximately 2561' (TOC @2611')</li> <li>5. RIH w/squeeze packer on 2 3/8" EUE tubing. Set packer above performed on the performance of t</li></ul>	follows: ations.

