

OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO 88240

May 21, 1971

Texas Pacific Oil Co., Inc.
P. O. Box 1069
Hobbs, New Mexico

Attention: Mr. Sheldon Ward

Gentlemen:

When you submitted your Notice of Intention to Drill on your Will Cary Well No. 9 located in Unit E of Section 22, T-22-S, R-37-E, you stated that the oil string would be set at 7400 feet with 950 sacks, which would have brought the top of the cement back to approximately 3120 feet from ground level. You actually set 4½" at 7303 feet with 75 sacks of cement. This cementing program does not adequately protect all pay zones in the area. I am particularly concerned with the Queen formation which is being waterflooded in the immediate area. Injected water from an offset injection well could reach the wellbore on this well, go up and down the hole, and find its way in porosity other than the Queen. This could also result in the charging of the salt section, which we certainly cannot permit.

Therefore, it will be necessary that you re-enter this well in the very immediate future and, at a minimum, perforate the casing below the base of the Queen, and cement through these perforations with adequate cement to cover the Queen and tie back to a point at least 600 feet above the pay in the Queen formation in this area.

Yours very truly,

OIL CONSERVATION COMMISSION

Joe D. Ramey
Supervisor, District 1

JDR/mc

HOBBES, NEW MEXICO 88340

701 4-2 854

TEXAS PACIFIC OIL CO., INC.
P.O. BOX 1880
HOUSTON, TEXAS

... ..

— 1935 —

[illegible]

1. The first of these is the fact that the Commission has not yet received any information from the Government of the United States regarding the results of its investigation of the activities of the American Friends Service Committee in the Philippines. It is therefore requested that the Commission be kept advised of any developments in this regard.

[illegible][illegible]

1950.