

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Kirby Exploration Company of Texas		8. Farm or Lease Name Vivian
3. Address of Operator P. O. Box 1745 Houston, Texas 77251		9. Well No. R-8542 21/1/88
4. Location of Well UNIT LETTER F 1787 FEET FROM THE north LINE AND 1787 FEET FROM THE west LINE, SECTION 30 TOWNSHIP 22S RANGE 38E NMPM.		10. Field and Pool, or Wildcat Drinkard Wantz Granite Wash
15. Elevation (Show whether DF, RT, GR, etc.) GR - 3329'		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Recomplete adding Abo perfs.

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is currently producing from perfs. in Granite Wash (7256'-84') and Drinkard (6391'-6448').
9-28-87 POH w/tbg rods and pump.
RIH w/tbg & packer and check TD. Swab test G.W. for 3 hr. test.
POH w/tbg & pkr and set retrievable CIBP @ 7050'. G. W. perfs @ 7256'-84'.
RIH w/csg gun & perf with 21 shots (6626'-6993') Abo.
RIH w/tbg & pkr & swab test.
Acidize with 5000 gals 15% HCl. Test for show.
Prepare to frac.
Run survey.
Allow well to clean up and run IPT.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Regulatory Supervisor DATE 9-21-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE SEP 22 1987

CONDITIONS OF APPROVAL, IF ANY: