IERGY AND MINERALS DEPARTMENT	UL CONSERVATION DIVISION	
DISTRIBUTION		Form C-103
SANTA FE	P. O. BOX 2088	Revised 10-1-78
	SANTA FE, NEW MEXICO 87501	
U.S.O.S.		5a. Indicate Type of Lease
LAND OFFICE		State 🗶 🛛 🖌 🗖 🗖 🖉 🖉
OPERATOR		5. State Oll & Gas Lease No.
		State
ELINDDV.		
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DAILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT REBERVOIR. USE "APPLICATION FOR PERMIT _" FORM C-1011 FOR SUCH PROPOSALS.)		
01L [17] 6A8 [7]		7. Unit Agreement Name
	OTHER-	
Name of Operator		8. Farm or Lease Name
American Exploration Company		New Mexico "M" State
Address of Operator		9. Well No.
2100 RepublicBank Center Houston, TX 77002		58
Location of Well		10, Field and Pool, or Wildcat
ki 15	1 South 12/0	Langlia Mattix Sn P/O
UNIT LETTER 1.5	0 FEET FROM THE <u>SOuth</u> LINE AND <u>1360</u> ,	TEET FROM LUNGULE MULLIN SH. N/2
THE West LINE, SECTION.	<u>20</u> township <u>22S</u> range <u>37E</u>	ММРМ. (() () () () () () () () () () () () ()
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
	3380' (GL)	Lea AMM
Check Ap	propriate Box To Indicate Nature of Notice, Repor	t of Other Data
NOTICE OF INT	•	EQUENT REPORT OF:
FORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
H		ALTERING CASING
APORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
L OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
07HER		

The subject well has been PA/d as follows:

- 1/6/89 CIBP @ 3425'. (Top perforation @ 3482') Capped w/70' of class "C" cmt.
- 1/6/89 Howco circulated hole w/10# salt gel.
- 1/6/89 Howco to spot 50 sx class "C" @ 2500'. SI overnight.
- 1/7/89 Tag cmt plug @ 2440'. Contacted Jerry Sexton to approve plug.
- 1/7/89 Howco to establish circulation dn $5\frac{1}{2}$ " csg w/good returns on $5\frac{1}{2}$ " x 8 5/8" annulus. Pump 106 sx class "C" cmt w/good slurry to pit - did not displace $5\frac{1}{2}$ " csg. $5\frac{1}{2}$ " csg full of cmt from 323' to surface as well as $5\frac{1}{2}$ " x 8 5/8" annulus. Rig dn & rel all contractors.
- 1/9/89 Remove anchors. Clean location. Place dry hole marker on 5½" csg. Project complete.

I hereby certify that the information above is true and complete to the beat of my knowledge and belief.

Ra Rudle	OIL & GAS INSPECTOR	FFB 1 5 1989	
ADVED BY L M AUDIT	11/12		-

RECEIVED

JAN 12 1989

OCD H2835 Offi**ce**