

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
		<p>5. State Oil & Gas Lease No.</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator JOHN H. HENDRIX</p>		<p>8. Farm or Lease Name COSSATOT "B"</p>
<p>3. Address of Operator 403 WALL TOWERS WEST MIDLAND, TEXAS 79701</p>		<p>9. Well No. 3</p>
<p>4. Location of Well UNIT LETTER N 330 FEET FROM THE South LINE AND 2080 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 22 South RANGE 37 East NMPM.</p>		<p>10. Field and Pool, or Wildcat WANTZ GRANITE WASH</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3350 DF</p>		<p>12. County Lea</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
<p>PERFORM REMEDIAL WORK <input checked="" type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>
	<p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>
	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up service unit and pull tubing and packer.
2. Perforate Granite Wash formation at 7108', 7136', 7166', 7224', 7242', 7268 7286', 7302', 7322', 7336' with one 3/8" jet per interval.
3. Fracture the above perforations plus the old perforations from 7176' to 7420' with 20,000 gallons lease crude and 20,000 # sand.
4. Run tubing and packer.
5. Swab well to test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe D. Ramey TITLE Accountant DATE November 6, 1972

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE NOV 8 1972

CONDITIONS OF APPROVAL, IF ANY: