Energy, Minerals and Natural Resources   Serviced March 25, 1999   WELL API NO.   30-025-241579696   325 N. French Dr., Hobbs, NM 85246   OIL CONSERVATION DIVISION   1220 South St. Francis Dr.   Santa Fe, NM 87505   Sinder Green Feb.   Santa Fe, NM 87505   Sinder Green Feb.   Santa Fe, NM 87505   SINDRY NOTICES AND REPORTS ON WELLS   OIL OR TO DEEPENS OR PLOG BACK TO A DIFFERENT KESERVOIR, USE APPLICATION FOR PERMIT' (FORM C-101) FOR NUCL POR WELL OIL OF THE WARD OF T	Submit 3 Copies To Appropriate Distri	ct State of	f New Mexico			Form C-10
Main Common   Main	Office			ources		Revised March 25, 19
OIL CONSERVATION DIVISION   Summark   Division   Divi	District I		-	WEL		
1220 South St. Francis Dr.   STATE   FEE			ATATION DIVI	30-02	25-24157 <del>000</del>	<del>)-</del>
Santa Fe, NM 87505   6. State Oil & Gas Lease No.	1301 W. Grand Ave., Artesia, NM 882				dicate Type of	of Lease
Santa F, Not   Sant	District III			l		
2220 S. S. Francis Dr. Sama Fe, PAM   SIGN   SUNDRY NOTICES AND REPORTS ON WELLS		Santa I	Fe, NM 87505	6.	State Oil & G	as Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS BO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPERSON RELIGIBLY.  BO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPERSON RELIGIBLY.  BO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPERSON RELIGIBLY.  BO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPERSON RELIGIBLY.  Elliott B-20  Elli	1220 S. St. Francis Dr., Santa Fe, NM					
DO NOT USE THIS PORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PULIG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PULIG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PULIG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PULIG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PULIG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION TO BE A WELL OCATION TO THE POOL TO THE	87505	THE PERCENT AND PE	ON MELLS	7 1	ease Name or	Unit Agreement Nam
Elliott B-20   Section	SUNDRY N	OTICES AND REPORTS OF	JN WELLS EPEN OR PLUGBAC	1	case radine of	O 7 15. 00
Elliott B-20  I. Type of Well: Oil Well Gas Well Other Oil Well Gas Well Other Oil Well Gas Well Other  S. Name of Operator Finley Resources, Inc.  3. Address of Operator Finley Resources, Inc. 3. Address of Operator Finley Resources, Inc. 3. Address of Operator Finley Resources, Inc. 3. Address of Operator Finley Resources, Inc. 3. Address of Operator Inc. Letter F   1980 feet from the North   Inc and 2246 feet from the West   Inc. Section 20	(DO NOT USE THIS FORM FOR PRI	PPLICATION FOR PERMIT" (FO	RM C-101) FOR SUCH	l		
Oil Well	PROPOSALS.)			Ellio	tt B-20	
2. Name of Operator Finley Resources, Inc.  3. Address of Operator 1308 Lake Street. Ste. 200, Fort Worth, Texas. 76102  4. Well Location Unit Letter F   1980 feet from the North line and 2246 feet from the West line Section 20 Township 228 Range 37E NMPM County Lea  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3382'  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   COMPLETION   CASING TEST AND   CASING TEST AND   COMPLETION   CEMENT JOB    OTHER: Perforate   OTHER:   OTHER:   OTHER:    OTHER: Perforate   OTHER:   OTHER:   OTHER:   OTHER:    OTHER: Perforate   OTHER:   OTHER:   OTHER:   OTHER:    OTHER: Perforate   OTHER:   OT	1. Type of Well:					
2. Name of Operator 3. Address of Operator 13. Langtie Mattix Seven Rivers  4. Well Location  Unit Letter F : 1980 feet from the North line and 2246 feet from the West line Section 20 Township 228 Range 37E NMPM County Lea  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3382'  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ADDRESSEQUENT REPORT OF: PEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS ABANDONMENT  TEMPORARILY ABANDON CHANGE PLANS COMPLETION CEMENT JOB  OTHER: Perforate  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date o starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' - 3,764'. Proposed to add upper Queen interval 3,436' - 3,332'. Stimulate with 1000 gals 15% HCL acid, 100 bobs. slick water frac with 1/8 - 1/4# sand per gal. Produce all perforations together. Shout date 3/24/03 or ASAP  1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE Amanda TITLE: Production & Operations Engineer DATE 3/20/03  Tolephone No. (817) 336-1924 ext. 27	Oil Well 🗶 Gas Well	Other		0 1	Iall No	
Pool name or Wildcat   Langlic Mattix Seven Rivers	2. Name of Operator			1		
Langlie Matrix Seven Rivers   1980   feet from the   North   line and   2246   feet from the   West   line						Wildcat
Well Location	3. Address of Operator					
Unit Letter F : 1980 feet from the North line and 2246 feet from the West line  Section 20 Township 22S Range 37E NMPM County Lea  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3382'  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENT OF CHA		rt Worth, Texas 76102		Lang	zne mattix se	VOII RIVOIS
Section 20 Township 22S Range 37E NMPM County Lea  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3382'  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   COMPLETION   CASING TEST AND CEMENT JOB    OTHER: Perforate   OTHER: OTHER   OTHER: OTHER   OTHER    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' - 3,764'. Proposed to add upper Queen interval 3,436' - 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 - 1/4# sand per gal. Produce all perforations together. Show the doctor of the best of my knowledge and belief.  SIGNATURE   June   Junes L. Nance   TITLE: Production & Operations Engineer   DATE 3/20/03    Telephone No. (817) 336-1924 ext. 27	4. Well Location					
Section 20 Township 22S Range 37E NMPM County Lea  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3382'  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   COMPLETION   CASING TEST AND CEMENT JOB    OTHER: Perforate   OTHER: OTHER   OTHER: OTHER   OTHER    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' - 3,764'. Proposed to add upper Queen interval 3,436' - 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 - 1/4# sand per gal. Produce all perforations together. Show the doctor of the best of my knowledge and belief.  SIGNATURE   June   Junes L. Nance   TITLE: Production & Operations Engineer   DATE 3/20/03    Telephone No. (817) 336-1924 ext. 27	_	1000 5 45 41	Nowth	ine and 2246	feet from	the West line
10. Elevation (Show whether DR, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND CEMENT JOB    OTHER: Perforate   OTHER:   OTHER:   OTHER:   OTHER:    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' - 3,764'. Proposed to add upper Queen interval 3,436' - 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 - ½# sand per gal. Produce all perforations together.   STORT DOT   STORT DATE   STORT D	Unit LetterF	:1980feet from th	neNorun	ille allu2240_		. the, est
10. Elevation (Show whether DR, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND CEMENT JOB    OTHER: Perforate   OTHER:   OTHER:   OTHER:   OTHER:    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' - 3,764'. Proposed to add upper Queen interval 3,436' - 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 - 1/4# sand per gal. Produce all perforations together. Start data 3/24/o3 or ASAP  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE	20	Township	22S Rano	e 37E	NMPM	County Lea
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CEMENT JOB    OTHER: Perforate   OTHER:   OTHER:   OTHER:    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' - 3,764'. Proposed to add upper Queen interval 3,436' - 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 - 1/4# sand per gal. Produce all perforations together. Start data 3/24/o 3 or ASAP  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE	Section 20	10 Elevation (Char	whother DR RKE			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB    OTHER: Perforate   OTHER: OTHER:   OTHER: OT			Whether Dr., ran	, 111, 014, 1111,		
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE COMPLETION   CASING TEST AND CEMENT JOB    OTHER: Perforate   OTHER: OTHER   OTHER: OTHER   OTHER: Perforate   OTHER: OTHER   OTHER: Perforate   OTHER: OTHER   OTHER: OTHER   OTHER   OTHER: OTHER   OT	11 01	al- Assessments Poy to	Indicate Nature	of Notice Reno	ort or Other	Data
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   COMPLETION   CASING TEST AND   CEMENT JOB    OTHER: Perforate   OTHER:   OTHER:   Including estimated date of starting any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' - 3,764'. Proposed to add upper Queen interval 3,436' - 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 - ½# sand per gal. Produce all perforations together. Shout dott 3/24/03 or ASAP  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE	II. Che	CK Appropriate Box to	Indicate Nature	SHRSEO	LIENT RE	PORT OF
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING CEMENT JOB CEMENT JOB OTHER: Perforate OTHER: Perforate OTHER: OTHER: COMPLETION OTHER: COMPLETION OTHER: COMPLETION OTHER: COMPLETION OTHER: COMPLETION OTHER: COMPLETION: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' - 3,764'. Proposed to add upper Queen interval 3,436' - 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 - 1/4# sand per gal. Produce all perforations together. Stant data 3/24/03 or ASANDONATIVE FOR THE PRODUCTION OF THE BENEFIT OF T			DEN DEN			ALTERING CASING
ABANDONMENT  ABANDONMENT  ABANDONMENT  ABANDONMENT  ABANDONMENT  CASING TEST AND  CEMENT JOB  OTHER:	PERFORM REMEDIAL WORK	C PLUG AND ABANDO		EDIAL WORK	لحبا	, ,
ABANDONMENT  ABANDONMENT  ABANDONMENT  ABANDONMENT  ABANDONMENT  CASING TEST AND  CEMENT JOB  OTHER:	TEMPORARIL V ARANDON	CHANGE DI ANS	□ COM	MENCE DRILLING	OPNS.□	
OTHER: Perforate  OTHER: Perforate  OTHER: O	TEMPORARILY ABANDON	☐ CHANGE PLANS	_		_	ABANDONMENT
OTHER: Perforate  OTHER: Perforate  OTHER: O	PULL OR ALTER CASING	☐ MULTIPLE				
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' – 3,764'. Proposed to add upper Queen interval 3,436' – 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 – 1/4# sand per gal. Produce all perforations together.  Start date 3/24/03 or ASAP  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  James J. Hames TITLE: Production & Operations Engineer  Type or print name James L. Nance  Telephone No. (817) 336-1924 ext. 27  (This space for State use)	TOLL OICHLE CONTO		CEM	ENT JOB		
2. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Current Interval: 3,552' – 3,764'. Proposed to add upper Queen interval 3,436' – 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 pobls. slick water frac with 1/8 – 1/4# sand per gal. Produce all perforations together.  Start date 3/24/03 or ASAP  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  James L. Nance  Title: Production & Operations Engineer  DATE 3/20/03  Type or print name James L. Nance  Telephone No. (817) 336-1924 ext. 27  [This space for State use]			M OTH	ED.		
Starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach welloof diagram of proposed completions recompilation.  Current Interval: 3,552' – 3,764'. Proposed to add upper Queen interval 3,436' – 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 – ½# sand per gal. Produce all perforations together.  Start data 3/24/03 or ASAP  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  SIGNATURE  James J. Hamil TITLE: Production & Operations Engineer  Type or print name James L. Nance  Telephone No. (817) 336-1924 ext. 27  (This space for State use)	OTHER: Perforate			-t-il- and give no	tinent dates	including estimated da
Current Interval: 3,552' – 3,764'. Proposed to add upper Queen interval 3,436' – 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 – 1/4# sand per gal. Produce all perforations together.  Stant cate 3/24/03 or ASAP  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  James J. Horney  TITLE: Production & Operations Engineer  Telephone No. (817) 336-1924 ext. 27  This space for State use)	<ol><li>Describe proposed or com</li></ol>	pleted operations. (Clearly	state an pertment c	etails, and give per	e diagram of	proposed completion of
Current Interval: 3,552' – 3,764'. Proposed to add upper Queen interval 3,436' – 3,532'. Stimulate with 1000 gals 15% HCL acid, 100 bbls. slick water frac with 1/8 – 1/4# sand per gal. Produce all perforations together. Start date 3/24/03 or ASAP  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE	starting any proposed work	i). SEE RULE 1103. For N	Autiple Completion	is. Attach wendor	c diagram or	proposed compresses
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  TITLE: Production & Operations Engineer  Title: Operations Engineer	recompilation.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  TITLE: Production & Operations Engineer  Title: Operations Engineer						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  TITLE: Production & Operations Engineer  Title: Operations Engineer						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  TITLE: Production & Operations Engineer  Title: Operations Engineer		A) Dd.tdd.ymmom (	Jugan interval 3 43	s' = 3.532' Stimu	late with 1000	gals 15% HCL acid,
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE    James L.   TITLE: Production & Operations Engineer   DATE 3/20/03	Current Interval: 3,552' - 3,764	1/4 and not got Produce	all perforations too	ether Start	date 3/2	24/03 on AS
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE	bbls, slick water frac with 1/8 -	- 1/4# sand per gai. Produce	all perforations tog	ciner. Siapot		17 0 11 1
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE						<u>h</u>
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE						/ // // // // // // // // // // // // //
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE						23.5
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE						***
TITLE: Production & Operations Engineer DATE 3/20/03  Type or print name James L. Nance Telephone No. (817) 336-1924 ext. 27  (This space for State use)						, ED
TITLE: Production & Operations Engineer DATE 3/20/03  Type or print name James L. Nance Telephone No. (817) 336-1924 ext. 27  (This space for State use)						Francis
TITLE: Production & Operations Engineer DATE 3/20/03  Type or print name James L. Nance Telephone No. (817) 336-1924 ext. 27  (This space for State use)						Franco Aco Aco
Type or print name James L. Nance  (This space for State use)  ON GINATISIONED BY  DATE: 0. 2002	II. I would that the inform	ation shove is true and com	plete to the best of	my knowledge and	belief.	h-Hoobs
Type or print name James L. Nance  (This space for State use)  ON GINATISIONED BY  DATE: 0. 2002	I hereby certify that the inform	ation above is true and com	plete to the best of	my knowledge and	belief.	Francis OCO
(This space for State use)	I hereby certify that the inform	ation above is true and com				h Hopps
(This space for State use)  ON GINATIFICATION ED BY	I hereby certify that the inform SIGNATURE	ation above is true and com		ion & Operations	Engineer	DATE 3/20/0
DATE C 2002	SIGNATURE fame	ot. Hance		ion & Operations	Engineer	DATE 3/20/0
APPPROVED BY  Conditions of approval, if any:  OF FIELD REPRESENTATIVE HISTAFF MANAGED  OC FIELD REPRESENTATIVE HISTAFF	SIGNATURE fame  Type or print name James I	ot. Hance		ion & Operations	Engineer	DATE 3/20/0
Conditions of approval, if any:  OC FIELD REPRESENTATIVE II/STAFF MANAGEMENT OC FIELD REPRESENTATIVE II/STAFF	SIGNATURE fame  Type or print name James I	. Nance	TITLE: Produc	ion & Operations	Engineer	DATE 3/20/0
OC FIELD REPRESENTATIVE 11/STATE	SIGNATURE James I  Type or print name James I  (This space for State use)	. Nance	TITLE: Product	ion & Operations   Teleph	Engineer none No. (81	DATE 3/20/0
	SIGNATURE James I  Type or print name James I  (This space for State use)  APPPROVED BY	. Nance	TITLE: Product	ion & Operations   Teleph	Engineer none No. (81	DATE 3/20/0
	SIGNATURE James I  Type or print name James I  (This space for State use)  APPPROVED BY	. Nance	TITLE: Product	ion & Operations   Teleph	Engineer none No. (81	DATE 3/20/0
	SIGNATURE James I  Type or print name James I  (This space for State use)  APPPROVED BY	. Nance	TITLE: Product	ion & Operations   Teleph	Engineer none No. (81	DATE 3/20/0
	SIGNATURE James I  Type or print name James I  (This space for State use)  APPPROVED BY	. Nance	TITLE: Product	ion & Operations   Teleph	Engineer none No. (81	DATE 3/20/0
	SIGNATURE James I  Type or print name James I  (This space for State use)  APPPROVED BY	. Nance	TITLE: Product	ion & Operations   Teleph	Engineer none No. (81	DATE 3/20/0